

Map of Grinder Pumps
(NTS)

The following grinder pump locations (SD 5) are located in and outside the FEMA 100-year flood plain and were identified as needing immediate repair (full replacement including vault) based on recent inspections.

Grinder Pump Location	Repair Date
1. 18395 Piney Point Road, Piney Point MD	7/26/2024
2. 18151 River Road, Tall Timbers MD 20690	7/17/2024
3. 18237 River Road, Tall Timbers MD 20690	7/25/2024
4. 45105 Deagles Boat Yard Rd, Tall Timbers MD 20690	8/13/2024
5. 45054 Deagles Boat Yard Rd, Tall Timbers MD 20690	8/14/2024
6. 17785 River Shore Drive Tall Timbers MD 20690	7/18/2024
7. 17795 River Shore Drive, Tall Timbers MD 20690	7/15/2024
8. 17959 River Shore Drive, Tall Timbers MD 20690	7/24/2024
9. 44477 Tall Timbers Road, Tall Timbers MD 20690	7/16/2024
10. 46006 Crowder Lane, Piney Pointy MD **	7/29/2024
11. 45158 A Street, Tall Timbers Md 20690	8/6/2024
12. 44318 Finnacom Road, Tall Timbers Md 20690	7/23/2024
13. 46036 Sheaffer Lane Piney Point MD 20674 **	7/30/2024
14. 46048 Sheaffer Lane Piney Point MD 20674 **	9/19/2024

** St. George's Island

ADDRESS_1	Location	METCOM_	Model	Type	Notes	NOTES2	Sanitary_District	Cost_Center	Property_ID	Owner	LifeCycleStatus	Install_Date
44472	44472 FINNACOM ROAD	PA12Y	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902010119	METCOM	Active	1990-95
44438	44438 FINNACOM ROAD	PA12Z	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902018098	METCOM	Active	1990-95
18521	18521 HERRING CREEK ROAD	PA13G	E1	DUPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020343	METCOM	Active	1990-95
44294	44294 FINNACOM ROAD	PA13H	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902012944	METCOM	Active	1990-95
18521	18521 HERRING CREEK ROAD	PA13I	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020343	METCOM	Active	1990-95
18521	18521 HERRING CREEK ROAD	PA13J	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020343	METCOM	Active	1990-95
18521	18521 HERRING CREEK ROAD	PA13K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020343	METCOM	Active	1990-95
18521	18521 HERRING CREEK ROAD	PA13L	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020343	METCOM	Active	1990-95
18521	18521 HERRING CREEK ROAD	PA13M	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020343	METCOM	Active	1990-95
18103	18103 RIVER ROAD	PA16C	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902013576	METCOM	Active	1990-95
18111	18111 RIVER ROAD	PA16E	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902000555	METCOM	Active	1990-95
18125	18125 RIVER ROAD	PA16F	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902011824	METCOM	Active	1990-95
18102	18102 RIVER ROAD	PA16G	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 2 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902017229	METCOM	Active	1990-95
18097	18097 RIVER ROAD	PA16K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902018438	METCOM	Active	1990-95
18075	18075 WILLIAM HOWARD WAY	PA16L	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902022087	METCOM	Active	1990-95
18399	18399 PINEY POINT ROAD	PA18C	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902011484	METCOM	Active	1990-95
18395	18395 PINEY POINT ROAD	PA18D	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902011484	METCOM	Active	1990-95
45044	45044 DEAGLES BOATYARD RD	PA18T	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902000822	METCOM		
45054	45054 DEAGLES BOATYARD RD	PA18U	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902013398	METCOM		
45130	45130 DEAGLES BOATYARD RD	PA18V	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902015501	METCOM		
17714	17714 PINEY POINT RD	PA18X	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902012316	METCOM		
45105	45105 DEAGLES BOATYARD RD	PA18Y	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902014378	METCOM		
45098	45096 DEAGLES BOATYARD RD	PA18Z	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902041030	METCOM		
45096	45096 DEAGLES BOATYARD RD	PA19A	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902041030	METCOM		
45068	45068 LOIS MARIE LN	PA19C	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902033380	METCOM		
45050	45050 LOIS MARIE LN	PA19D	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902030012	METCOM		
17939	17939 SAINT GEORGES PARK RD	PA19E	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902007797	METCOM		
17947	17947 SAINT GEORGES PARK RD	PA19F	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902017709	METCOM		
45054	45054 TROOPERS RD	PA19I	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902019027	METCOM		
44918	18030 MARSTELLERS COVE WAY	PA19M	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020483	METCOM		
44922	18030 MARSTELLERS COVE WAY	PA19N	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902021382	METCOM		
44939	44939 SHORE DR	PA19P	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902007436	METCOM		
44945	44945 SHORE DR	PA19R	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902012618	METCOM		
17787	17777 GRACE LN	PA19S	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902038242	METCOM		
17777	17777 GRACE LN	PA19T	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902038234	METCOM		
17909	17909 CLARKE RD	PA19V	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902009161	METCOM		
17905	17905 CLARKE RD	PA19W	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902009161	METCOM		
17879	17879 CLARKE RD	PA19X	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902015579	METCOM		
17841	17841 CLARKE RD	PA21A	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902021242	METCOM		
17785	17785 CLARKE RD	PA21C	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902002175	METCOM		
17769	17769 CLARKE RD	PA21D	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902008084	METCOM		
17747	17747 CLARKE RD	PA21E	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902001446	METCOM		
17618	17618 CLARKE RD	PA21J	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902022168	METCOM		
17614	17614 CLARKE RD	PA21K	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902015072	METCOM		
17619	17619 CLARKE RD	PA21M	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902003457	METCOM		
44703	44703 LIGHTHOUSE RD	PA21N	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902015641	METCOM	Active	1985-90
44730	44730 LIGHTHOUSE RD	PA21P	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020017	METCOM		
44737	44737 LIGHTHOUSE RD	PA21Q	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902019795	METCOM	Active	1985-90
44733	44733 LIGHTHOUSE RD	PA21R	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902007002	METCOM	Active	1985-90
44729	44729 LIGHTHOUSE RD	PA21S	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902010208	METCOM	Active	1985-90
44725	44725 LIGHTHOUSE RD	PA21T	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902000644	METCOM	Active	1985-90
44721	44721 LIGHTHOUSE RD	PA21U	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902000636	METCOM	Active	1985-90
44719	44719 LIGHTHOUSE RD	PA21V	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902040662	METCOM	Active	2000-05
44908	44908 LIGHTHOUSE RD	PA21W	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	19020?????	METCOM	Active	1985-90
44908	44908 LIGHTHOUSE RD	PA21X	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	19020?????	METCOM	Active	1985-90
44924	44924 LIGHTHOUSE RD	PA21Y	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	19020?????	METCOM	Active	1985-90
44940	44940 LIGHTHOUSE RD	PA21Z	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902015587	METCOM	Active	1985-90
44945	44945 LIGHTHOUSE RD	PA22A	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902035014	METCOM	Active	1985-90
44952	44948 LIGHTHOUSE RD	PA22B	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902007452	METCOM	Active	1985-90
44958	44958 LIGHTHOUSE RD	PA22C	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902006472	METCOM	Active	1985-90
44962	44962 LIGHTHOUSE RD	PA22D	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902007517	METCOM		
44966	44962 LIGHTHOUSE RD	PA22E	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902008440	METCOM	Active	1985-90
44970	44970 LIGHTHOUSE RD	PA22F	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902014513	METCOM	Active	1985-90
44974	44978 LIGHTHOUSE RD	PA22G	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902010194	METCOM	Active	1985-90
44980	44984 LIGHTHOUSE RD	PA22H	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	19020?????	METCOM	Active	1985-90
44988	44988 LIGHTHOUSE RD	PA22I	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902012901	METCOM	Active	1985-90
44996	44996 LIGHTHOUSE RD	PA22J	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902014505	METCOM	Active	1985-90
45008	45008 LIGHTHOUSE RD	PA22K	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902002892	METCOM	Active	1985-90
45020	45020 LIGHTHOUSE RD	PA22L	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902003201	METCOM	Active	1985-90
45024	45024 LIGHTHOUSE RD	PA22M	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020424	METCOM	Active	1985-90
45030	45030 LIGHTHOUSE RD	PA22N	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902007118	METCOM	Active	1985-90
45046	45046 LIGHTHOUSE RD	PA22P	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902002965	METCOM	Active	1985-90
45056	45056 LIGHTHOUSE RD	PA22Q	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902017970	METCOM	Active	1985-90
45062	45062 LIGHTHOUSE RD	PA22R	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902018748	METCOM	Active	1985-90
45076	45076 LIGHTHOUSE RD	PA22S	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902006448	METCOM	Active	2020-2025
45080	45080 LIGHTHOUSE RD	PA22T	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902013002	METCOM	Active	1985-90
45086	45086 LIGHTHOUSE RD	PA22U	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902012839	METCOM	Active	1985-90
45092	45092 LIGHTHOUSE RD	PA22V	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902011956	METCOM	Active	1985-90
45098	45098 LIGHTHOUSE RD	PA22W	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902011956	METCOM	Active	1985-90
45112	45112 LIGHTHOUSE RD	PA22X	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020335	METCOM	Active	1985-90
45122	45122 LIGHTHOUSE RD	PA22Y	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902014416	METCOM	Active	1985-90
45138	45138 LIGHTHOUSE RD	PA22Z	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902018497	METCOM	Active	1985-90
45144	45144 LIGHTHOUSE RD	PA23A	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902000660	METCOM	Active	1985-90
45150	45148 LIGHTHOUSE RD	PA23B	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	19020?????	METCOM	Active	1985-90
45154	45154 LIGHTHOUSE RD	PA23C	OTHER	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902016583	METCOM	Active	1985-90
45158	45158 LIGHTHOUSE RD	PA23D	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020475	METCOM	Active	1985-90
45164	45164 LIGHTHOUSE RD	PA23E	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902010372	METCOM	Active	1985-90
45168	45168 LIGHTHOUSE RD	PA23F	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902014734	METCOM	Active	1985-90
45174	45174 LIGHTHOUSE RD	PA23G	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902014823	METCOM	Active	1985-90
45184	45184 LIGHTHOUSE RD	PA23H	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902012642	METCOM	Active	1985-90
45196	45196 LIGHTHOUSE RD	PA23I	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902010631	METCOM	Active	1985-90
45216	45216 LIGHTHOUSE RD	PA23J	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020181	METCOM	Active	1985-90
45226	45226 LIGHTHOUSE RD	PA23K	OTHER	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902018268	METCOM	Active	1985-90
45230	45230 LIGHTHOUSE RD	PA23L	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902004402	METCOM	Active	1985-90
45246	45246 LIGHTHOUSE RD	PA23M	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902021323	METCOM	Active	1985-90
45245	45245 LIGHTHOUSE RD	PA23N	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902017067	METCOM	Active	1985-90
45151	45151 LIGHTHOUSE LN	PA23P	UNKNOWN	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902007835	METCOM	Active	1985-90
45157	45157 LIGHTHOUSE LN	PA23Q	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020823	METCOM	Active	1985-90
17263	17263 OAKWOOD LODGE LN	PA23R	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902035634	METCOM	Active	1985-90
17267	17267 OAKWOOD LODGE LN	PA23S	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902005697	METCOM	Active	1985-90
45296	45296 LIGHTHOUSE RD	PA23T	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902004119	METCOM	Active	1985-90
17337	17337 GODDARDS LN	PA23U	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902021021	METCOM	Active	1985-90
17357	17357 GODDARDS LN	PA23V	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	19020032279	METCOM	Active	1985-90
44765	44765 LIGHTHOUSE ROAD	PA23W	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902033852	METCOM	Active	1995-00
17497	17497 RIVER DR	PA24D	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020661	METCOM		
17494	17494 RIVER DR	PA24E	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902013835	METCOM		
17495	17495 HOLLY ST	PA24K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS		METCOM		
17526	17526 RIVER DR	PA24L	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902018012	METCOM		
45360	45360 SAINT GEORGES AVE	PA24M	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902011883	METCOM		
17537	17537 RIVER DR	PA24N	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902001128	METCOM		
17549	17549 RIVER DR	PA24P	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020556	METCOM		
17559	17559 RIVER DR	PA24Q	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020548	METCOM		
17575	17575 RIVER DR	PA24R	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902002329	METCOM		
17580	17580 RIVER DR	PA24S	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902034832	METCOM		
17585	17585 RIVER DR	PA24T	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902010542	METCOM		
45383	45383 SAINT GEORGES AVE	PA24U	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902009048	METCOM		
17465	17465 POPLAR ST	PA24V	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902017962	METCOM		
17451	17451 POPLAR ST	PA24W	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902002345	METCOM		
17428	17428 POPLAR ST	PA25A	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902006162	METCOM		
17420	17420 POPLAR ST	PA25B	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902017059	METCOM		
45425	45425 SAINT GEORGES AVE	PA25I	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902013169	METCOM		
45438	45438 SAINT GEORGES AVE	PA25J	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902017598	METCOM		
45441	45441 SAINT GEORGES AVE	PA25K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902018888	METCOM		
45451	45451 SAINT GEORGES AVE	PA25L	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902013177	METCOM		
45455	45455 SAINT GEORGES AVE	PA25N	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902008777	METCOM		
45461	45461 SAINT GEORGES AVE	PA25P	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902002930	METCOM		
45473	45473 SAINT GEORGES AVE	PA25R	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902012616	METCOM		
17591	17591 RIVER DR	PA25S	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902026120	METCOM		
16994	16998 PINEY POINT RD	PA26F	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002103	METCOM	Active	1985-90

TOTAL
291 Grinder Pumps in Flood Plains

Methodology:
Sort by Sanitary District equal to PINEY POINT
and Notes equal to 100 YEAR FLOODPLAIN

16980	16980	PINEY POINT RD	PA26G	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002634	METCOM	Active	1985-90	
condemned	16995	PINEY POINT RD	PA26H	E1	DUPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001484	METCOM	Inactive	1985-90	
16979	16979	PINEY POINT RD	PA26I	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001468	METCOM	Active	1990-95	
16983	16983	PINEY POINT RD	PA26J	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001476	METCOM	Active	1985-90	
16977 not	16977	PINEY POINT RD	PA26K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002251	METCOM	Inactive	1985-90	
16940	16940	PINEY POINT RD	PA26L	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002421	METCOM	Active	1985-90	
16876	16876	PINEY POINT RD	PA26M	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000461	METCOM	Active	1985-90	
16874	16874	PINEY POINT RD	PA26N	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000127	METCOM	Active	1985-90	
16800	16800	PINEY POINT RD	PA26P	MYERS	DUPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000550	METCOM	Active	2005-10	
17168	17168	TROT LINE WAY	PA26Q	E1	DUPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902041391	METCOM	Active	1985-90	
17170	17170	TROT LINE WAY	PA26R	E1	DUPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902041405	METCOM	Active	1985-90	
17191	17191	PINEY POINT RD	PA26X	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 2 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902009676	METCOM			
16760	16760	PINEY POINT RD	PA27F	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002545	METCOM	Active	1990-95	
16750	16750	PINEY POINT RD	PA27G	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002553	METCOM	Active	1990-95	
16712	16712	PINEY POINT RD	PA27H	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001212	METCOM	Active	1990-95	
16682	16678	PINEY POINT RD	PA27I	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000038	METCOM	Active	1990-95	
16662	16662	PINEY POINT RD	PA27J	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000747	METCOM	Active	1990-95	
16660	16660	PINEY POINT RD	PA27K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001875	METCOM	Active	1990-95	
16664	16664	PINEY POINT RD	PA27L	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001271	METCOM	Active	1990-95	
16638	16638	PINEY POINT RD	PA27M	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002162	METCOM	Active	1990-95	
16650	16650	PINEY POINT RD	PA27N	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002715	METCOM	Active	1990-95	
16646	16646	PINEY POINT RD	PA27P	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002707	METCOM	Active	1990-95	
16608	16608	PINEY POINT RD	PA27Q	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000968	METCOM	Active	1990-95	
16602	16602	PINEY POINT RD	PA27R	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000070	METCOM	Active	1990-95	
46014	46014	SHANTY POINT LN	PA27S	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000240	METCOM	Active	1990-95	
45967	45971	SHANTY POINT LN	PA27T	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000194	METCOM	Active	1990-95	
45968	45968	SHANTY POINT LN	PA27U	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000445	METCOM	Active	1990-95	
45962	45962	SHANTY POINT LN	PA27V	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001867	METCOM	Active	1990-95	
45958	45958	SHANTY POINT LN	PA27W	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000143	METCOM	Active	1990-95	
45956	45968	SHANTY POINT LN	PA27X	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000615	METCOM	Active	1990-95	
45954	45954	SHANTY POINT LN	PA27Y	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000712	METCOM	Active	1990-95	
16585	16585	PINEY POINT RD	PA27Z	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000666	METCOM	Active	1990-95	
45966	45966	OCONNORS LN	PA28A	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000097	METCOM	Active	1990-95	
45970	45970	NELSON LN	PA28B	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002146	METCOM	Active	1990-95	
45972	45972	OCONNORS LN	PA28C	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001360	METCOM	Active	1990-95	
46015	46015	OCONNORS LN	PA28D	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001751	METCOM	Active	1990-95	
16558	16558	PINEY POINT RD	PA28E	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000321	METCOM	Active	1990-95	
46006	46006	CROWDER LN	PA28F	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001883	METCOM	Active	1990-95	
46006	46006	OCONNORS LN\	PA28G	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000259	METCOM	Active	1990-95	
16562	16562	PINEY POINT RD	PA28H	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001883	METCOM	Active	1990-95	
16540	16540	PINEY POINT RD	PA28I	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000348	METCOM	Active	1990-95	
16512	16512	PINEY POINT RD	PA28J	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002073	METCOM	Active	1990-95	
16500	16500	PINEY POINT RD	PA28K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000224	METCOM	Active	1990-95	
46012	46012	CROWDER LN	PA28L	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001751	METCOM	Active	1990-95	
16538	16538	PINEY POINT RD	PA28M	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000348	METCOM	Active	1990-95	
condemed	16562	PINEY POINT RD	PA28N	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000348	METCOM	Active	1990-95	
16530	16530	PINEY POINT RD	PA28P	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001034	METCOM	Active	1990-95	
46030	46030	SHEAFFER LN	PA28Q	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000313	METCOM	Active	1990-95	
46048	46048	SHEAFFER LN	PA28R	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001530	METCOM	Active	1990-95	
46036	46036	SHEAFFER LN	PA28S	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001255	METCOM	Active	1990-95	
46015	46015	CROWDER LN	PA28T	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001131	METCOM	Active	1990-95	
46055	46055	SHEAFFER LN	PA28U	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001530	METCOM	Active	1990-95	
46059	46059	SHEAFFER LN	PA28V	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000135	METCOM	Active	1990-95	
46053	46053	SHEAFFER LN	PA28W	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001220	METCOM	Active	1990-95	
16498	16498	PINEY POINT RD	PA28X	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000267	METCOM	Active	1990-95	
16584	16584	PINEY POINT	PA28Z	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000879	METCOM	Active	1990-95	
16452	16378	PINEY POINT RD	PA29F	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002291	METCOM	Active	1990-95	
16378	16378	PINEY POINT RD	PA29K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002219	METCOM	Active	1990-95	
16450	16450	PINEY POINT RD	PA29L	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001018	METCOM	Active	1990-95	
16446	16446	PINEY POINT RD	PA29M	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000801	METCOM	Active	1990-95	
16432	16432	PINEY POINT RD	PA29P	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001050	METCOM	Active	1990-95	
16444	16444	PINEY POINT RD	PA29Q	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000801	METCOM	Active	1990-95	
16440	16440	PINEY POINT RD	PA29R	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000801	METCOM	Active	1990-95	
16434	16434	PINEY POINT RD	PA29S	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001506	METCOM	Active	1990-95	
16424	16424	PINEY POINT RD	PA29T	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002138	METCOM	Active	1990-95	
16424	16424	PINEY POINT RD	PA29U	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002138	METCOM	Active	1990-95	
16402	16402	PINEY POINT RD	PA29V	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000607	METCOM	Active	1990-95	
16384	16384	PINEY POINT RD	PA29W	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000763	METCOM	Active	1990-95	
16374	16374	PINEY POINT RD	PA29X	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000993	METCOM	Active	1990-95	
16346	16346	PINEY POINT RD	PA29Y	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000305	METCOM	Active	1990-95	
16340	16340	PINEY POINT RD	PA29Z	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000062	METCOM	Active	1990-95	
16332	16332	PINEY POINT RD	PA31A	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001123	METCOM	Active	1990-95	
16384	16384	BALL POINT RD	PA31B	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000763	METCOM	Active	1990-95	
16510	16510	BALL POINT RD	PA31C	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001352	METCOM	Active	1990-95	
16500	16500	BALL POINT RD	PA31D	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001174	METCOM	Active	1990-95	
16455	16455	SAYRE POINT RD	PA31E	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001786	METCOM	Active	1990-95	
16459	16459	SAYRE POINT LN	PA31F	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000119	METCOM	Active	1990-95	
16480	16480	SAYRE POINT RD	PA31G	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001093	METCOM	Active	1990-95	
16460	16460	SAYRE POINT RD	PA31H	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001093	METCOM	Active	1990-95	
16442	16442	BALL POINT RD	PA31I	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001980	METCOM	Active	1990-95	
16440	16440	BALL POINT RD	PA31J	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001832	METCOM	Active	1990-95	
16448	16448	BALL POINT RD	PA31K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001964	METCOM	Active	1990-95	
16451	16451	BALL POINT RD	PA31L	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000534	METCOM	Active	1990-95	
?	16444	BALL POINT RD	PA31M	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001964	METCOM	Active	1990-95	
16430	16430	BALL POINT RD	PA31N	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000151	METCOM	Active	1990-95	
16422	16422	BALL POINT RD	PA31P	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000283	METCOM	Active	1990-95	
16428	16428	BALL POINT RD	PA31Q	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000275	METCOM	Active	1990-95	
16418	16418	BALL POINT RD	PA31R	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001107	METCOM	Active	1990-95	
condemned	16402	BALL POINT RD	PA31S	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001778	METCOM	Active	1990-95	
16380	16380	BALL POINT RD	PA31T	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001549	METCOM	Active	1990-95	
163??	16408	BALL POINT RD	PA31U	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001115	METCOM	Active	1990-95	
163??	16384	BALL POINT RD	PA31V	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000542	METCOM	Active	1990-95	
16390	16390	BALL POINT RD	PA31W	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001670	METCOM	Active	1990-95	
16392	16392	BALL POINT RD	PA31X	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001433	METCOM	Active	1990-95	
16363	16363	BALL POINT RD	PA31Y	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000402	METCOM	Active	1990-95	
16431	16431	THOMAS RD	PA31Z	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000380	METCOM	Active	1990-95	
16416	16416	THOMAS RD	PA32A	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001840	METCOM	Active	1990-95	
16381	16381	THOMAS RD	PA32B	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000526	METCOM	Active	1990-95	
16384	16384	THOMAS RD	PA32C	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001069	METCOM	Active	1990-95	
16475	16475	HARMS WAY	PA32D	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001573	METCOM	Active	1990-95	
16465	16465	HARMS WAY	PA32E	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001573	METCOM	Active	1990-95	
16445	16445	HARMS WAY	PA32F	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002006	METCOM	Active	1990-95	
16443	16443	HARMS WAY	PA32G	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001679	METCOM	Active	1990-95	
16441	16441	HARMS WAY	PA32H	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000984	METCOM	Active	1990-95	
16262	16262	THOMAS RD	PA32K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002049	METCOM	Active	1990-95	
16231	16231	THOMAS RD	PA32P	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000593	METCOM	Active	1990-95	
16212 A	16212	THOMAS RD	PA32S	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000429	METCOM	Active	1990-95	
16212 B	16212	THOMAS RD	PA32T	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000429	METCOM	Active	1990-95	
1612 C	16212	THOMAS RD	PA32U	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000429	METCOM	Active	1990-95	
16197	16197	THOMAS RD	PA32V	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 2 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002111	METCOM	Active	1990-95	
16174	16174	THOMAS RD	PA32Z	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 2 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002332	METCOM	Active	1990-95	
16176	16176	THOMAS RD	PA33A	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001999	METCOM	Active	1990-95	
16180	16180	THOMAS RD	PA33B	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001662	METCOM	Active	1990-95	
16178	16178	THOMAS RD	PA33C	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001581	METCOM	Active	1990-95	
16124	16124	THOMAS RD	PA33J	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001646	METCOM	Active	1990-95	
16130	16130	THOMAS RD	PA33L	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000860	METCOM	Active	1990-95	
16144	16144	THOMAS RD	PA33M	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002057	METCOM	Active	1990-95	
16100	16100	THOMAS RD	PA33P	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000046	METCOM	Active	1990-95	
16088	16088	THOMAS RD	PA33Q	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001441	METCOM	Active	1990-95	
16084	16084	THOMAS RD	PA33S	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001859	METCOM	Active	1990-95	
16076	16076	THOMAS RD	PA33T	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001379	METCOM	Active	1990-95	
16056	16056	THOMAS RD	PA33U	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001298	METCOM	Active	1990-95	
16054	16054	THOMAS RD	PA33V	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000798	METCOM	Active	1990-95	
16054	16054	THOMAS RD	PA33W	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000798	METCOM	Active	1995-00	
16048	16048	THOMAS RD	PA33X	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001182	METCOM	Active	1990-95	
16048	16048	THOMAS RD	PA33Y	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001182	METCOM	Active	1990-95	
16040	16040	THOMAS RD	PA33Z	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001689	METCOM	Active	1990-95	
16032	16032	THOMAS RD	PA34A	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002294	METCOM	Active	1990-95	
16060	16060	CAMP MERRYELANDE RD	PA34B	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001395	METCOM	Active	1990-95	
16061	16061	CAMP MERRYELANDE RD	PA34C	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002464	METCOM	Active	1990-95	

16087	16087 THOMAS RD	PA34D	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001344	METCOM	Active		1990-95
16091	16091 THOMAS RD	PA34G	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001425	METCOM	Active		1990-95
16065	16065 CAMP MERRYELANDE RD	PA34H	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002456	METCOM	Active		2020-2025
16045	16045 CAMP MERRYELANDE RD	PA34I	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002693	METCOM	Active		1990-95
17265	17265 OAKWOOD LODGE LN	PA75A	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902015420	METCOM	Active		1985-90
45198	45198 LIGHTHOUSE RD	gp	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902010658	METCOM	Active		1985-90
45132	45132 LIGHTHOUSE RD	gp	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902014424	METCOM	Active		2000-05
45112	45112 LIGHTHOUSE RD	gp			100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS		METCOM			
45106	45106 LIGHTHOUSE RD	PA74Y	BARNES	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902030314	METCOM	Active		1990-95
00000	00000 LIGHTHOUSE RD	gp			100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS		METCOM			
44765	44767 HOTEL COVE LANE	PA74U	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902033852	METCOM	Active		1995-00
44767	44775 HOTEL COVE LANE	PA74V	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902033860	METCOM	Active		1995-00
44775	44783 HOTEL COVE LANE	PA74W	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902033879	METCOM	Active		2000-05
44715	44715 LIGHTHOUSE RD	PA74T	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902020033	METCOM	Active		2005-10
16165	16165 PINEY POINT RD	PA77G	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001336	METCOM	Active		1990-95
16490	16490 BALL POINT RD	PA77H	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002804	METCOM	Active		1990-95
16213	16213 THOMAS RD	PA77J	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000925	METCOM	Active		1990-95
16093	16093 THOMAS RD	PA77K	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000372	METCOM			1990-95
16730	16730 PINEY POINT RD	PA77P	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002502	METCOM	Active		1990-95
16894	16894 PINEY POINT RD	PA75C	E1	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909000291	METCOM	Active		1990-95
17160	17160 TROT LINE WAY	PA75D	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902041359	METCOM	Active		2000-05
17162	17162 TROT LINE WAY	PA75E	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902041367	METCOM	Active		2000-05
17164	17164 TROT LINE WAY	PA75F	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902041375	METCOM	Active		2000-05
17166	17166 TROT LINE WAY	PA75G	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902041383	METCOM	Active		2000-05
17172	17172 TROT LINE WAY	PA75H	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	19020	METCOM	Active		2000-05
44586	44586 OLIVER DR	PA74R	MYERS	SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1902004011	METCOM	Active		2010-15
16168	16168 PINEY POINT RD	PA77D		SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001085	METCOM	Active		2010-15
15914	15914 CAMP MERRYELANDE RD	PA77F	BARNES	OTHER	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002227	METCOM	Active		2020-2025
15914	16038 CAMP MERRYELANDE RD	PA77E		SIMPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002227	METCOM	Active		2000-05
16810	16810 PINEY POINT ROAD	PA81G	E1	DUPLEX	100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909002812	METCOM	Abandoned		2005-10
16127	16127 PINEY POINT RD A	PA82H	BARNES		100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001263	METCOM	Active		2020-2025
16127	16127 PINEY POINT RD B	PA82I	BARNES		100 YEAR FLOODPLAIN	CAT 1 STORM SURGE	PINEY POINT	44 PINEY POINT COLLECTIONS	1909001263	METCOM	Active		2020-2025

LIST OF GRINDER PUMP STATIONS INSPECTION REPORTS

1. River Shore Drive
2. Saint Georges Avenue
3. Saint Georges Park Road
4. Saint Georges Road
5. Sawdust Lane
6. Sayre Point Lane
7. Shallow Ford Court
8. Shanty Point Lane
9. Sheaffer Lane
10. Ships View Way
11. Shore Drive
12. Stark Drive
13. Steuart Petroleum Road
14. Tall Timbers Road
15. Thomas Road
16. Troopers Road
17. Walnut Street
18. Whitestone Drive
19. Whitestone Place
20. William Howard Way
21. Wind Whisper Way
22. 2nd Street
23. 3rd Street
24. 4th Street
25. A Street
26. Andover Estate Road
27. Arthur Fenwick Lane
28. Ball Point Road
29. Bellview Court
30. Blackwell Court
31. Blue Water Lane
32. Buggs Way
33. Camp Merryelande Road
34. Cedar Cove Lane
35. Clarke Road
36. Crowder Lane
37. Deagles Boatyard Road
38. Denton Road
39. Driftwood Drive
40. Finnacom Road
41. Giddings Street
42. Goddards Lane
43. Grace Lane
44. Harms Way
45. Herring Creek Road
46. Holly Street
47. Hotel Cove Lane
48. Lighthouse Lane
49. Lighthouse Road
50. Loblolly Court
51. Locust Grove Drive
52. Locust Street
53. Lois Marie Lane
54. Main Drive Way
55. Marstellars Cove Way
56. Morgan Brison Lane
57. Morgan Point Lane
58. Connor Lane
59. Oakland Avenue
60. Oakwood Lodge Lane
61. Old Tall Timbers Road
62. Oliver Drive
63. Peninsulas Court
64. Petite Point Lane
65. Pinetamare Way
66. Piney Point Road 1
67. Piney Point Road 2
68. Point Lookout Road- St Lukes Methodist Church
69. Poplar Street
70. River Drive
71. River Road
72. River Run Lane

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6971



Date of Inspection	1/30/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17877 2nd St.			
Weather Conditions	Rain	Snow	Sunny	~~Cloudy~~

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6751
32003

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials*** LN CB	
Inspection Number			
Property Address	17880 2nd St.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6844

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17884 2nd St.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6758

St. Mary's County MetCom

Grinder Pump Field Inspection Form

WO 31926

Date of Inspection	1/29/2024	***Inspector Initials***	LW CB
Inspection Number			
Property Address	17886 2nd St.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	~~Poor~~	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Power seems to be off in house. vault full

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6794
WO31935

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17888 2nd St.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

I&I coming in around inlet pipe
overhanging branches - nearby tree

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6599

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	***Inspector Initials***		
Inspection Number				
Property Address	17848 3rd Street			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6609

Date of Inspection	1/24/24	***Inspector Initials***	
Inspection Number			
Property Address	17856 3rd Street		
Weather Conditions	Rain	Snow	Sunny ~~Cloudy~~

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

2 Large Bushes covering up vault lid. In pictures
Roots covering up vault's inlet, cleared roots out of vault.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6691
WO31854

Date of Inspection	1/24/24		***Inspector Initials***	
Inspection Number				
Property Address	17857 3rd Street			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

The Buzzer was going bad in the panel, the Alarm Light works but the Alarm does not.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6983

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	***Inspector Initials***		
Inspection Number				
Property Address	17864 3rd Street			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6-143

WO 31920

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	17870 3rd St.			
Weather Conditions	Rain	Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Both audible and visual alarms not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6745
WO 31921

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17877 3rd St.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots growing in around discharge pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

67446

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	17879 3rd. St.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6747

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17881 3rd St.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6722

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	17837 4th Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6724
WO 31913

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	17838 4th St.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots growing in around inlet pipe
Both visual and audible alarms not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6709
WO 31906

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	17841 4th Street			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

I&I trickling in around inlet pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6713

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17842 4th Street			
Weather Conditions	Rain	Snow	~~Sunny~~	~~Cloudy~~

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6932

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	***Inspector Initials***	JB OB PP	
Inspection Number				
Property Address	17845 4th Street			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6931

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	***Inspector Initials***		
Inspection Number				
Property Address	17846 4th Street			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6933

Date of Inspection	1/24/24		***Inspector Initials***	
Inspection Number				
Property Address	17849 4th Street			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6984

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	2/6/24	***Inspector Initials***	LN
Inspection Number			
Property Address	17850 44 st		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6985

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	2/6/24	***Inspector Initials***	LN
Inspection Number			
Property Address	17853 4th st		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6986

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	2/6/24	***Inspector Initials***	LN
Inspection Number			
Property Address	17854 4th st		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6727
WO 31914

Date of Inspection	1/29/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	17856 4th St.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

✓

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Junction box is hanging down by cables in vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6909

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024 ***Inspector Initials*** LN CB
Inspection Number	17857 4th St
Property Address	Deagles Boat Yard Rd (By 3rd St. no address)
Weather Conditions	Rain Snow (Sunny) Cloudy

17857 4th St

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault? ✓

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	(Broken)	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.) ✓

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present? ✓

Yes	No

What is the condition of the electrical panel? ✓

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning? ✓

Yes	No	Present, but not tested

Is the visible alarm present and functioning? ✓

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	(No)

Are there any obvious signs of I&I (ie. clearwater flow)? ✓

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault does not have an address. Abandoned
Cover is cracked and broken. Full of water
side of road near 3rd St.

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6729
WO 31915

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17858 4th Street		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

I&I coming in around junction box pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6735
WO 31916

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17859 4th St.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault nearly underwater after rain

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6740
WO 31918

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	17861 4th St.			
Weather Conditions	Rain	Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	(Good)	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

(Yes)	No	Present, but not tested

Is the visible alarm present and functioning?

(Yes)	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	(No)

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vault is nearly underwater after rain

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

0708
WO 31905

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	45158 A St.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault cover cracked
I&I coming in around inlet pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6201

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.
Inspection Number			
Property Address	18920 Andover Estates Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Homeowner is not connected due to not paying bill.

No Immediate Action

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6203

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	EP.
Inspection Number			
Property Address	45136 Andover Estate Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6204

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.R.
Inspection Number			
Property Address	45146 Andover Estate Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6206

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24		***Inspector Initials***	E.P.
Inspection Number				
Property Address	45154 ~~Oakland Ter.~~ Andover Estate			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

The relay in the panel was not sitting upright.

Photos should be sent to ~~opadmin@metcom.org~~ with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

62056

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	DS	
Inspection Number				
Property Address	45157 Andover Estate Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Grinder Pump Lid was hit by a lawn mower not cracked, but it is cut up.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6185

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam
Inspection Number			
Property Address	46148 ARTHUR FENWICK LANE		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF ELEC. PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6183

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam
Inspection Number			
Property Address	46152 AUBURN FARMER LANE		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6184

Date of Inspection	1/11/24	***Inspector Initials***	MLM	
Inspection Number				
Property Address	46154 ARTHUR FARWICK LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6187

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16363 BALL POINT RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6193

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/9/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16380 BALL POINT RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6188

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	16384 BALLPOINT RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES SURROUNDING VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6189

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	8/8/24	***Inspector Initials***	mam
Inspection Number			
Property Address	~~16386~~ 16386 BALL RD		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6190

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	16390 BALL POINT RD			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6191

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	16393 BALL POINT RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6192

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24	***Inspector Initials***	mar	
Inspection Number				
Property Address	16395 Ball Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

61860

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mrm
Inspection Number			
Property Address	16402 ~~16126~~ BALL POINT RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES WITHIN 5FT OF VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6194

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/9/24		***Inspector Initials***	
Inspection Number				
Property Address	16406 Ball Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6194

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/9/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16408 BALL POINT RD			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

61196

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/9/21		***Inspector Initials***	mem
Inspection Number				
Property Address	16418 BALL POINT RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6197

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/9/24		***Inspector Initials***	mem
Inspection Number				
Property Address	16422 BALL POINT RD.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6198
WO 31636

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16430 BALL POINT RD.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

[redacted]	(No)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6199

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	MM	
Inspection Number				
Property Address	16440 Ball Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6202
WO 31661

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16443 Ball Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE CLEANED OUT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6205
W/O - 31662

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mtm
Inspection Number			
Property Address	16444 Ball Point Rd.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

PANEL NOT ATTACHED TO THE HOUSE AND CONDUIT BROKEN
VAULT NEEDS TO BE CLEANED

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6207
WO 31663

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16448 BALL POINT RD.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT WAS FULL, TURNED ON PUMP AND IT WORKED PROPERLY
LEFT BREAKER ON.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6200

WO 316660

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24		***Inspector Initials***	mam
Inspection Number				
Property Address	~~11654~~ 11654 BALL POINT RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

3 BOLTS BROKEN ON TOP OF VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6209
WO - 316664

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16490 BALL POINT RD		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers (circled)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good (circled)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good (circled)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes (circled)	No (circled)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NEEDS A RISER INSTALLED ON VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6210

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	10500 Ball Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6211

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16510 Ball Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

62164

WO/ 31708

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	SS ICR
Inspection Number			
Property Address	44561 Bellview Ct.		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers (circled)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent (circled)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent (circled)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes (circled)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Vault needs a riser. lid was buried in the front yard garden.
Alarm Light work, Alarm does not

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

62265
WO / 31709

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DJ CR
Inspection Number			
Property Address	44572 Bellview Ct.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Bushes blocking access to the panel
Alarm Light works but no sound

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

02166
WO 31710

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	JJ CR
Inspection Number			
Property Address	44580 Belliview Ct		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Bush blocking access to panel
Roots in vault, cleared the vault up, took roots out

Alarm light is on, No SOUND

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

02567

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DJ CL	
Inspection Number				
Property Address	44587 Bellview Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Large Bush blocking access to panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6268
WO 31712

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	JS CR
Inspection Number			
Property Address	44590 Bellview Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Bush blocking access to the panel.
Vault Cover is cracked in multiple spots.
Alarm Light works no Alarm Sound

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

10269
WO 31713

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	BB CR
Inspection Number			
Property Address	44600 Bellview Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Vault cover is cracked, Bushes covering up the control panel
Alarm Float Light works but Alarm does not sound.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

C0277

WO 31717

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/16/24	***Inspector Initials***	DS CR
Inspection Number			
Property Address	44601 Bellview Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Float & Light DO NOT WORK

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6270
WO 31714

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	JW CR
Inspection Number			
Property Address	44610 Bellview Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

~~Are there any~~ obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Light & Alarm for Float DO NOT WORK
Also the connections inside the vault could be re-done

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6271

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	SS CR
Inspection Number			
Property Address	44624 Bellview Ct		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

There is 1 Bush blocking access to the panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6272
WO 31715

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DD CR
Inspection Number			
Property Address	44631 Bellview Ct		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Multiple Bushes covering up ALL Access to the panel
The Alarm Float Light & Alarm DO NOT WORK

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6273

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	JH CL
Inspection Number			
Property Address	44634 Bellview Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

(2) 7ft Bushes covering up the whole panel blocking all access to the panel.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6274
WO 31716

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	~~NS~~ CF
Inspection Number			
Property Address	44637 Bellview Ct.		
Weather Conditions	Rain Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm works on Float but light for Alarm on panel does not

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

0276

Date of Inspection	1/18/24	***Inspector Initials***	JH CR
Inspection Number			
Property Address	44639 Bellview Ct.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6278

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	WC	
Inspection Number				
Property Address	44645 Bellview Ct			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6779

Date of Inspection	1-25-24		***Inspector Initials***	RH LN
Inspection Number				
Property Address	45053 Blackwell ct			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6778

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24		***Inspector Initials***	RH CN
Inspection Number				
Property Address	45073 Blacksmell ct			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6777

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	***Inspector Initials***	RH LN
Inspection Number			
Property Address	45089 Blackwell ct		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6774

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	***Inspector Initials***	MWM	
Inspection Number				
Property Address	45200 BLUE WATER LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6775

Grinder Pump Field Inspection Form

WO 31928



Date of Inspection	1/25/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	45210 BLUE WATER LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

COVER ON VAULT IS BROKEN

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6773
WO 31927



Date of Inspection	11/25/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	45215 BLUE WATER LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT TO VAULT NEEDS TO BE CLEANED OUT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6776

Date of Inspection	11/25/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	45230 BLUE WATER LN			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6279
WO 31720

St. Mary's County MetCom

Grinder Pump Field Inspection Form



Date of Inspection	1/18/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45214 Buggs Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

visual alarm light not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6280

WO 31721

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	45224 Buggs Way		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Small roots growing into vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6281
WO 31723

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	45234 Buggs Way		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots growing into vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6282

St. Mary's County MetCom

Grinder Pump Field Inspection Form



Date of Inspection	1/18/2024	***Inspector Initials*** LN	CB
Inspection Number			
Property Address	~~45434~~ Buggs Way 45244		
Weather Conditions	Rain	Snow	Sunny / Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

ID 6180

WO 31617

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	January 8 2024 (0750) ***Inspector Initials*** BMG S.Green
Inspection Number	
Property Address	15914 Camp Merryelande RD Piney Point MD 20674
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

I&I on Entry pipe into well. (pictured)
Pump chains need to be replaced with stainless steel chain to prevent rust.

Repairs needed (if any) and estimated schedule for completion:

- see above noted -

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6369

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16036 CAMP MERRYMANDE RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6370

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24		***Inspector Initials***	MAM
Inspection Number				
Property Address	16045 CAMP MERRY GLANDE RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT IS SURROUNDED BY GRASS IN FRONT YARD

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6371



Date of Inspection	1/22/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	16060 CAMP MERRYLANDS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NO POWER GOING TO THE GRINDER PUMP THE DWELLING IS UNOCCUPIED.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6372

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16061 CAMP MERRYLANDER RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6373

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24	***Inspector Initials***	MAM	
Inspection Number				
Property Address	16065 Camp Merryelands Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6858

Grinder Pump Field Inspection Form

WO 31951

Date of Inspection	1/24/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	18623 ~~Piney Point Rd.~~ Cedar Cove Ln			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this? Submergible (duplex)

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	(Poor)	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Many roots growing in all around wet well

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6379

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17614 Clarke Rd.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vault is in a very small fenced in area touching wooden fence

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6380

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17618 Clarke Rd.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6283

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17619 Clarke Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

ABANDONED

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6381

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17026 Clarke Rd.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

small fence built around vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6352

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials*** LN CB		
Inspection Number				
Property Address	17628 Clarke Rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Near by trees with low overhanging branches

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6857

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17640 Clarke Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	(Broken)	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vent broken off top of vault cover
ESP switch for alarm
vault was buried between buildings under dirt

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

0286

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17660 ~~Frank's Place~~	Clarke Rd		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6284
WO 3724

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17730 Clarke Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots growing into vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6285

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17746 Clarke Rd.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6384

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/19/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17747 Clarke Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6385

St. Mary's County MetCom

Grinder Pump Field Inspection Form

WO 31778

Date of Inspection	1/19/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17752 Clarke Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6386

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/19/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17765 Clarke Rd.		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6387.

WO 31779

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17766 Clarke Rd.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault cover has a hole in it

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6390

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/19/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17769 Clarke Rd.		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6392

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17780 Clarke Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6395

WO 31780

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17785 Clarke Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	(Broken)	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault cover chipped off on one bolt hole
Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

C398

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17812 Clarke Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

ESP switch for alarm

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6405

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	17819 Clarke Rd.
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6409

WO 31784

Date of Inspection	1/22/2024	***Inspector Initials*** LN CB		
Inspection Number				
Property Address	17827 Clarke Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	(Broken)	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vent broken off top of vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6413

Date of Inspection	1/22/2024	***Inspector Initials*** LN CB		
Inspection Number				
Property Address	17841 Clarke Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

ESP switch for alarm

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6416
WO 31789

Date of Inspection	1/22/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	17846 Clarke Rd.
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	(Broken)	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault cover chipped by one bolt hole

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6418

Grinder Pump Field Inspection Form

WO 31790

Date of Inspection	1/22/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17861 Clarke Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots growing into vault near inlet pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6421

Grinder Pump Field Inspection Form

Date of Inspection	1 | 22 | 2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	17869 Clarke Rd.
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6423

WO 31792

Date of Inspection	1/22/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17879 Clarke Rd.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vent broken off top of vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6425

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	17905 Clarke Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17909 Clarke Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6212
WO 31682

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	46001 CROWDER LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

ROOTS GROWING IN VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6213
WO 31665

Date of Inspection	1/12/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	46006 CROWDER LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

TOP OF VAULT IS BROKEN CAN ATTACH RISER BOLTS BROKEN

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6214

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/12/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	46013 CROWDER LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF PANEL.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6215

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/21/24	***Inspector Initials***	mm
Inspection Number			
Property Address	46015 CROWDER LANE		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS CLEANING OUT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6605

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	***Inspector Initials***	RH SS
Inspection Number			
Property Address	45033 Deagles boatyard Rd		
Weather Conditions	Rain Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(~~Non-Vented~~)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(~~Good~~)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6981
WO 31997

Date of Inspection	1/24/24	***Inspector Initials***	RH SS
Inspection Number			
Property Address	45037 Deogle's boatyard Rd		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	~~Fair~~	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Light works, Alarm does not.

Vault is very dirty with buildup at bottom of vault, needs to be cleaned.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6982

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	***Inspector Initials***		
Inspection Number				
Property Address	45041 Deagles Boatyard Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6968
W/O: 31984

Date of Inspection	1/30/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	45044 Beagles Boat Yard Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

I&I trickling in around inlet pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6604



Date of Inspection	1/24/24	***Inspector Initials***		
Inspection Number				
Property Address	45053 Deagles Backyard Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6848
WO 31949

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	45054 Deagles Boat Yard Rd.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault broken at the top under the cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6602

WO 31855

Date of Inspection	1/24/24		***Inspector Initials***	
Inspection Number				
Property Address	45065 ~~3rd Street~~ Deagles Boatyard Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Top Bracket Clip for panel is broke off. took a picture
Alarm Switch Light works no sound

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6849

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45096 Deagles Boat Yard Rd			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault is nearly underwater after rain

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6850
WO 31974

45098

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB
Inspection Number	45098		
Property Address	~~45098~~ Deagles Boat Yard Rd.		
Weather Conditions	Rain ~~45098~~ Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault is underwater after rain

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6969 :P
w/o: 31985

Date of Inspection	1/31/2024	***Inspector Initials*** LN CB		
Inspection Number				
Property Address	45105 Deagles Boat Yard Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault is in swamp - Flooded
Installed riser
VAULT NEEDS TO BE MOVED IMMEDIATELY

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6851
WO 31950

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45106 Deagles Boat Yard Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots growing into vault around inlet pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6852

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	45110 Deagles Boat Yard Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6853

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	46122 Deagles Boatyard Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6854

Date of Inspection	1/29/2024	***Inspector Initials*** LN CB		
Inspection Number				
Property Address	46130 Deagles Boat Yard Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6977
32002

Date of Inspection	1/22/2024	***Inspector Initials***	DR EP	
Inspection Number				
Property Address	18611 Dentonrd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No



What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6439
WO 31796

Date of Inspection	1/22/2024	***Inspector Initials***	DR EP	
Inspection Number				
Property Address	18631 Denton rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

~~Alarm does not work~~

Alarm does not work

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6441

Date of Inspection	1/22/2024	***Inspector Initials***	DR EP	
Inspection Number				
Property Address	18635 Denton rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

69760

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	DR EP	
Inspection Number				
Property Address	18645 denton rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

ID: 6333

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DJ CR
Inspection Number			
Property Address	17550 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6334
WO 31745

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DF CR
Inspection Number			
Property Address	17561 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers (circled)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair (circled)	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor (circled)	Immediate Action

Is an isolation valve present?

Yes (circled)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

~~Are there~~ any obvious signs of I&I (ie. clearwater flow)?

No ~~signs~~ of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

~~Bottom Ears on rail are missing~~, Vault walls ~~are~~ were covered with roots,

Inlet ~~is~~ was also covered with roots, need to get I&I out here

Pulled out as much roots that we could

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6335

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	AR	CC
Inspection Number				
Property Address	17562 Driftwood Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6336

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***		
Inspection Number				
Property Address	17567 Driftwood Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

1 Bush blocking access to panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6337

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	JJV CR
Inspection Number			
Property Address	17573 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6338

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DJ CR	
Inspection Number				
Property Address	17593 Driftwood Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6339

WO 31746

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DS CR
Inspection Number			
Property Address	17665 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Light works but not Alarm

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6340

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***		
Inspection Number				
Property Address	17610 Driftwood Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6341

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DJ CR
Inspection Number			
Property Address	17615 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

1 Bush blocking access to panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6342

WO 31747

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	SS CR
Inspection Number			
Property Address	17625 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Float Alarm Light works but Alarm does not

Vault cover is cracked as well

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6343

WO 31748

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	JK CR
Inspection Number			
Property Address	17635 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Float Light works but buzzer does not

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6344

Date of Inspection	1/18/24	***Inspector Initials***	JH CR
Inspection Number			
Property Address	17660 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Bush Blocking access to panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6345
WO 31749

Date of Inspection	1/18/24	***Inspector Initials***	JH CR
Inspection Number			
Property Address	17674 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm light works but no sound

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6975

Date of Inspection	1/31/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17684 Driftwood Dr.		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

ondition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault was buried under dirt and mulch next to bushes. Dug it up

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

63416

WO 31750

Date of Inspection	1/18/24	***Inspector Initials***	JJ CR
Inspection Number			
Property Address	17690 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Light works Alarm does not sound
Vault - Grinder Pump Rail is broken

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6377

Date of Inspection	1/22/24	***Inspector Initials***	BB RH	
Inspection Number				
Property Address	17710 Driftwood Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

1 Large Bush blocking access to panel.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6378

WO 31777

Date of Inspection	11/22/24	***Inspector Initials***		
Inspection Number				
Property Address	17744 Driftwood Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

The vault is broken in pieces at the top right under the lid.
2 Bushes blocking panel access

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6374

WO 31775

Date of Inspection	1/22/24	***Inspector Initials***	RJH
Inspection Number			
Property Address	17878 Driftwood Drive		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Grinder Pump vault needs a riser out of the yard.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6375

Date of Inspection	1/22/24	***Inspector Initials***	
Inspection Number			
Property Address	17926 Driftwood Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6376
WO 31960

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	~~DD~~ TH
Inspection Number			
Property Address	18016 Driftwood Drive		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	~~Barnes~~	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Barnes pump with a myers lid.
Alarm Float DOES NOT WORK AT ALL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6749

Date of Inspection	1|26|2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address	44294 Finnacom Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6750
WO 31923

Date of Inspection	1/26/2024	***Inspector Initials***	FS CB	
Inspection Number				
Property Address	44318 Finnicom Rd.			
Weather Conditions	Rain	Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	~~Retrofit~~	E1

What is the condition of the vault?

Excellent	~~Good~~	Fair	~~Poor~~	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	~~Broken~~	offset

What type of cover is installed?

~~Vented~~	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	~~Good~~	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Top of vault below cover is broken

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6752

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address	44338 Firmacom Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6753

Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address	44356 Firnacom Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6754

Date of Inspection	1/26/2024	***Inspector Initials***	FS	CB
Inspection Number				
Property Address	44378 Finnacom Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6756

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address	44400 Finnacom Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6755

Date of Inspection	1/26/2024		***Inspector Initials***	FS CB
Inspection Number				
Property Address	44424 Finnacom Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vault is in the middle of some shrubs

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6757

Date of Inspection	1/26/2024	***Inspector Initials***	FS CB
Inspection Number			
Property Address	~~44472~~ Finnacom Rd.		
Weather Conditions	Rain 44472 Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

During high tide and rain events, vault cover is underwater

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6253

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.
Inspection Number			
Property Address	18162 Giddings Street		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6216

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24		***Inspector Initials*** E.P.	
Inspection Number				
Property Address	18165 Giddings St			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6254

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.	
Inspection Number				
Property Address	18166 Gibbons St.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6217

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24		***Inspector Initials*** E.P.	
Inspection Number				
Property Address	18172 Giddings St.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.S
Inspection Number			
Property Address	18173 Giddings St.		
Weather Conditions	Rain	Snow	Sunny

ID: 6218
W/O#: 31667

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm float light is on when made, BUT there is no alarm sound.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6219

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24		***Inspector Initials*** E.P.	
Inspection Number				
Property Address	18179 Giddings St.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6220
WO 31668

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1 | 11 | 2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	17837 Goddards Ln
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	(Broken)	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

No audible alarm on panel
alarm light still works

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6972
W/O: 31987

Date of Inspection	1/30/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17367 Goddards Ln.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	(Broken)	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

s an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6222

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024		***Inspector Initials***	
Inspection Number				
Property Address	17362 Goddards Ln.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6532

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/19/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17726 Grace Ln			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Has ESP switch cannot test alarm

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6533

Grinder Pump Field Inspection Form

Date of Inspection	1/19/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17731 Grace Ln.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6534

Date of Inspection	1/19/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	17747 Grace Ln			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6535
WO 318628

Date of Inspection	1/19/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17777 Grace Ln.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Alarm light not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6537

Date of Inspection	1/19/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	17787 Grace Ln.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6502

Date of Inspection	1\23\24	***Inspector Initials***	mam
Inspection Number			
Property Address	16443 HARRIS WAY		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6503

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	MTM	
Inspection Number				
Property Address	16445 HARMS WAY			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF ELECTRICAL PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6505

Date of Inspection	1\23\24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16465 Harms Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT IN THE BUSHES

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6596

Date of Inspection	1/23/24		***Inspector Initials***	mcm
Inspection Number				
Property Address	16475 Harms Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT WAS BURIED IN DIRT AND MULCH HAD TO DIG OUT.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6970

Date of Inspection	1/30/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	18363 Herring Creek Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

s an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6759

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address	18386 Herring Creek Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6760

Grinder Pump Field Inspection Form

WO 31924

Date of Inspection	1/26/2024 ***Inspector Initials*** FS CB
Inspection Number	
Property Address	18395 Herring Creek Rd.
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	(Broken)	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault cover broken on one side

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6761

Date of Inspection	1/26/2024	***Inspector Initials***	FS CB	
Inspection Number				
Property Address	18401 Herring Creek Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6762

Grinder Pump Field Inspection Form

Date of Inspection	1 | 26 | 2024 ***Inspector Initials*** FS CB
Inspection Number	
Property Address	18419 Herring Creek Rd.
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6763

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address	18461 Herring Creek Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6764

WO 31925

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address	18521 Herring Creek Rd. 1			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this? duplex

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6765

Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address	18621 Herring Creek Rd. 2			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6766

Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024	***Inspector Initials***	FS CB
Inspection Number			
Property Address	18621 Herring Creek Rd. Cottage 1		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6767

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024		***Inspector Initials*** FS	CB
Inspection Number				
Property Address 2	18521 Herring Creek Rd. Cottage 2			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6768

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address 3	18621 Herring Creek Rd. cottage 3			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6769

Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address *	18521 Herring Creek Rd. cottage 4			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6237

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17495 Holly St			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6239

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17508 Holly St.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vault cover has a crack
part of vault is chipped off. Does not affect I&I

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6241
WO 31678

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB
Inspection Number			
Property Address	44767 Hotel Cove Ln		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Audible alarm not sounding wires exposed inside vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6242

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB	
Inspection Number				
Property Address	44776 Hotel Cove Ln			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vault cover is cracked

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6243
WO 31680

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB
Inspection Number			
Property Address	44783 Hotel Cove Ln		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Tall seagrass around vault cover. wires exposed inside vault Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

60221

WO 316669

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	46151 Lighthouse Ln		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

NO light or audible alarm
vault cover under large metal lid in asphalt

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

0225

WO 31670

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45157 Lighthouse Ln.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

No audible alarm sound

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6/24

WO 31671

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB	
Inspection Number				
Property Address	44703 Lighthouse Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Audible alarm not sounding. Visual alarm light still works

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6225
WO 31672

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP LB	
Inspection Number				
Property Address	44715 Lighthouse Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Audible alarm not sounding. Visual alarm light still works.
Panel and vault cover both surrounded by tall seagrass

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

60226

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB	
Inspection Number				
Property Address	44719 Lighthouse Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Shrubs partially blocking panel

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6227

St. Mary's County MetCom

WO 31673

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB
Inspection Number			
Property Address	44721 Lighthouse Rd.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6229

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB	
Inspection Number				
Property Address	44725 Lighthouse Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6230

WO 31674

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB
Inspection Number			
Property Address	44729 Lighthouse Rd.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault cover cracked. wires exposed in vault junction box
Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6228

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB
Inspection Number			
Property Address	44730 Lighthouse Rd.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6231

WO- 31675

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB	
Inspection Number				
Property Address	44733 Lighthouse Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

wires exposed in vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6232

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB	
Inspection Number				
Property Address	44737 Lighthouse Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6233

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/2024	***Inspector Initials***	EP	CB
Inspection Number				
Property Address	44741 Lighthouse Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6234
WO 31733

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB	
Inspection Number				
Property Address	44765 Lighthouse Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

both audible and visible alarms not working.
contacted maintenance

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6974
W/O: 31988

Date of Inspection	1/30/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	44908 Lighthouse Rd.
Weather Conditions	Rain Snow Sunny ~~Cloudy~~

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

s an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault flooded, no power to panel

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6255
WO 31688

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17		***Inspector Initials***	DR EP
Inspection Number				
Property Address	44924 Lighthouse rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

No lid on junction box in vault
Alarm does not work

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6256
WO 31690

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17		***Inspector Initials***	DR EP
Inspection Number				
Property Address	44940 Light House rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Panel behind Fence

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

junction box inside vault needs lid

Vault lid is not bolted down

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6257

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17		***Inspector Initials***	DCR EP
Inspection Number				
Property Address	44945 lighthouse rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Shrubs around the vault

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6258

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17	***Inspector Initials***	DR EP
Inspection Number			
Property Address	44948 Light house rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6259
WO 31692

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17	***Inspector Initials***	DCR EP
Inspection Number			
Property Address	44952 Lighthouse rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

no lid on junction Box

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6260

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Come Back

Date of Inspection	1/17	***Inspector Initials***	DR EP
Inspection Number			
Property Address	44958 Light house rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6261
WO 31693

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17	***Inspector Initials***	DLL BP
Inspection Number			
Property Address	44962 Light house rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6262

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17		***Inspector Initials***	DR EP
Inspection Number				
Property Address	44966 Light house rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

62603
WO 31694

Grinder Pump Field Inspection Form

Date of Inspection	1/17	***Inspector Initials***	RJR EP
Inspection Number			
Property Address	44970 Light house rd		
Weather Conditions	Rain	Snow	Sunny / Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

no power at the [redacted] panel

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6429

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/8/24	***Inspector Initials***	DR CRH
Inspection Number			
Property Address	44974 Light house rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6430
WO 31793

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DR RH	
Inspection Number				
Property Address	44978 Lighthouse Rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	[redacted]	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vicegrips holding the rail in place needs to be fixed

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6332
WO 31732

Date of Inspection	1/16/24	***Inspector Initials***	EP
Inspection Number			
Property Address	44980 Lighthouse Rd.		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Vault Lid is cracked up. The rails INSIDE the vault are cracked up. The Isolation Valve is broken as well

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6431

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DR RH
Inspection Number			
Property Address	44984 Lighthouse rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6432

WO 31794

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	DB RH
Inspection Number			
Property Address	44988 Light house rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Bad Alarm Float Rocks Covering Vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6435

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/8/24	***Inspector Initials***	DM BH
Inspection Number			
Property Address	44996 Light house rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6430
WO 31795

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	DM RH
Inspection Number			
Property Address	45008 Lighthouse rd		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	~~Immediate Action~~

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Tree in the way of Pump

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Wire burnt off run Compasator Capacitor

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6434

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/8/24	***Inspector Initials***	DR BH
Inspection Number			
Property Address	45020 Lighthouse Rd		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64136

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	DB RH
Inspection Number			
Property Address	45024 Lighthouse Rd		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers (circled)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good (circled)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good (circled)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes (circled)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6437

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/8/24	***Inspector Initials***	DR RH
Inspection Number			
Property Address	45030 Lighthouse Rd		
Weather Conditions	Rain Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6438

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	DR RH	
Inspection Number				
Property Address	45048 Lighthouse Rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6440
WO 31797

Date of Inspection	11/18/24	***Inspector Initials***	DRAH
Inspection Number			
Property Address	45056 Light house rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Panel behind Fence

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

needs lid on junction Box in vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6442

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DB RH	
Inspection Number				
Property Address	45062 Lighthouse RD			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6451

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	DR RH
Inspection Number			
Property Address	45076 Lighthouse Rd		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6450

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	DR RH
Inspection Number			
Property Address	45880 Light House Rd		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

, 6448
WO 31799

Date of Inspection	11/8/2024	***Inspector Initials***	DR RH
Inspection Number			
Property Address	45086 Lighthouse Rd		
Weather Conditions	Rain Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	~~Barnes~~	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	(Good)	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

(Yes)	No	Present, but not tested

Is the visible alarm present and functioning?

(Yes)	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	(No)

Are there any obvious signs of I&I (ie. clearwater flow)?

(No signs of I&I)	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Junction Box needs l.d.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64446

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	DB RH
Inspection Number			
Property Address	45092 Lighthouse Rd		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6444
WO 31798

Date of Inspection	11/18/24	***Inspector Initials***	DR RH
Inspection Number			
Property Address	45098 Lighthouse Rd		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Needs new alarm float.

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6452

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/8/24	***Inspector Initials***	DB RH
Inspection Number			
Property Address	45106 Light House Rd		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6427

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/8/24	***Inspector Initials***	DR KH	
Inspection Number				
Property Address	45112 Lighthouse Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6424

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24		***Inspector Initials*** DR RH	
Inspection Number				
Property Address	45122 Light House RD			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6422
WO 31791

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	DR RH	
Inspection Number				
Property Address	45132 Light house Dr			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

lid has to be replaced.

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6420

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/8/24	***Inspector Initials***	RH DR
Inspection Number			
Property Address	45138 Lighthouse Rd		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6419

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	RH DB
Inspection Number			
Property Address	45144 Light House RD		
Weather Conditions	Rain Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6417

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24		***Inspector Initials***	RH DB
Inspection Number				
Property Address	45148 Lighthouse Rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6415

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	RH DB	
Inspection Number				
Property Address	~~US 4~~ 45154 Lighthouse Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6414
WO 31788

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	RH DR
Inspection Number			
Property Address	45158 Lighthouse Rd		
Weather Conditions	Rain Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Rail Bracket need to be replaced

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6412
WO 31786

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	RH DR	
Inspection Number				
Property Address	45164 Lighthouse Rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	~~Broken~~	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Tree right on top of vault and The lid is broken and needs to be replaced

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6411

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	BH DB	
Inspection Number				
Property Address	45168 Lighthouse Rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64128

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	RH DB	
Inspection Number				
Property Address	45174 Lighthouse Rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64158
WO 31805

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	DR EP	
Inspection Number				
Property Address	45184 Light house rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Rocks and shrubs in front of Panel

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Alarm light works no sound

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6453
WO 31801

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	DR EP	
Inspection Number				
Property Address	45196 Light house rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Isolation Valve Brake

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6456

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024	***Inspector Initials***	DR EP	
Inspection Number				
Property Address	45198 Lighthouse rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6235
WO 319164

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	45216 Lighthouse Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault? ✓

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.) ✓

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present? ✓

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault full, house under construction

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

0454
WO 31803

Date of Inspection	1/22/2024 ***Inspector Initials*** DR EP
Inspection Number	
Property Address	45226 Lighthouse rd
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Isolation valve Broken

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6236
NO 316716

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45230 Lighthouse Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Alarm light not working
audible alarm still sounds

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6238

WO 31677

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	46245 Lighthouse Rd.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Visual alarm light not working. Audible alarm still sounds

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6455
WO 31804
See WO# 31679

Date of Inspection	1/22/2024	***Inspector Initials***	DR EP	
Inspection Number				
Property Address	45296 Light house rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Alarm light works no sound

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6240
WO 31679

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	46296 Lighthouse Rd.
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	(Broken)	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vault cover is old and chipped
Alarm sound doesn't work, light still works

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6347

WO 31751

Date of Inspection	1/18/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	46100 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Leaking around inlet pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6348

WO 31752

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45111 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots growing into vault near inlet pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6349
WO 31753

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	45112 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots growing into vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6350

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45121 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6351
WO 31754

Date of Inspection	1/18/2024	***Inspector Initials*** LN CB	
Inspection Number			
Property Address	48122 Loblolly Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots growing into vault near inlet
Both audible and visual alarm not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6352
WO 31755

Date of Inspection	1/18/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45131 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6353

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45141 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6354

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials*** LN CB		
Inspection Number				
Property Address	45142 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6355
WO 31756

Date of Inspection	1/18/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	45149 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Alarm light does not work
some small roots growing around inlet
small edge chipped off of vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6356

WO 31757

Date of Inspection	1/18/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	45152 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Alarm light not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6357

Grinder Pump Field Inspection Form



Date of Inspection	1/18/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45155 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6358

Date of Inspection	1/18/2024	***Inspector Initials*** LN CB	
Inspection Number			
Property Address	45161 Loblolly Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6359

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45162 Loblolly Ln.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6360

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	45171 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6361

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials*** LN CB	
Inspection Number			
Property Address	45172 Loblolly Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6362
WO 31759



Date of Inspection	1/18/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45181 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Alarm light not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6363

WO 317160

Date of Inspection	1/18/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	45182 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Alarm light not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6364

WO 31761

Date of Inspection	1/18/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	45191 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Alarm light not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6365

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45192 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault? ✓

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.) ✓

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present? ✓

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

ABANDONED

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6366



Date of Inspection	1/18/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	45195 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6367

WO 31762

Date of Inspection	1/18/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45198 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Top of vault is cracked and missing a small chunk
audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6368

WO 31763

Date of Inspection	1/18/2024	***Inspector Initials***	UN CB	
Inspection Number				
Property Address	45199 Loblolly Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

visual alarm light not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6246

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.	
Inspection Number				
Property Address	45444 Locust Grove Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What ~~type of~~ pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6247

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.
Inspection Number			
Property Address	45455 Locust Grove Dr.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6248
WO 31687

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.
Inspection Number			
Property Address	45464 Locust Grove Dr.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm float does not light up OR sound off when it's made.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6249

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.
Inspection Number			
Property Address	45465 Locust Grove Dr		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

There are 2 Full Size Bushes covering up the panel, making it difficult to reach the panel, and open the panel.

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6250

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E P.
Inspection Number			
Property Address	45472 Locust Grove Dr.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6251

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.	
Inspection Number				
Property Address	45480 Locust Grove Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6252

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.
Inspection Number			
Property Address	45486 Locust Grove Dr.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6244

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	45382 Locust St.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Tall seagrass around vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6245

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	45395 Locust St.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Pump has ESP switch for alarm

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6748

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	45076 Lois Marie Ln.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6549

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB
Inspection Number			
Property Address	44814 Main Drive Way		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6550

Date of Inspection	1/12/2024	***Inspector Initials***	EP CB	
Inspection Number				
Property Address	44822 Main Drive Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6922

WO 31977

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24		***Inspector Initials***	
Inspection Number				
Property Address	18025 ~~Shore Dr.~~ Marstellers Cove Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

No isolation valve

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

69926

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***		
Inspection Number				
Property Address	18030 ~~Shore Dr.~~ Marstellers Cove Way			
Weather Conditions	Rain	Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

Yes	~~No~~	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6859 a
6860 b

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	***Inspector Initials***	LN BH
Inspection Number			
Property Address	45019 Morgan Brisco Ln		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6770

Date of Inspection	11/25/24		***Inspector Initials***	MEM
Inspection Number				
Property Address	45325 MORGAN POINT LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6771

Date of Inspection	1/25/24		***Inspector Initials*** m&m	
Inspection Number				
Property Address	45345 Morgan Point [redacted] Lane			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6772

Grinder Pump Field Inspection Form

Date of Inspection	11/25/24		***Inspector Initials***	mwm
Inspection Number				
Property Address	45355 MORGAN POINT [redacted] LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6577

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	45966 OCONNORS LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6578

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mam
Inspection Number			
Property Address	45970 OLDFIELDS LANE		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6580

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/12/24	***Inspector Initials***	mtm
Inspection Number			
Property Address	45972 OLD MORSLAND		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6582
WO 31841

Date of Inspection	1/12/24	***Inspector Initials***	MLM	
Inspection Number				
Property Address	46006 OLD MOOSE LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	~~No~~

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NEED TO REPLACE COVER AND RISER

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6583

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mcm	
Inspection Number				
Property Address	46015 OCONNOR LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6556

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P	
Inspection Number				
Property Address	18199 Oakland Ave			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any ~~accessibility issues~~ (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

The Panel is in between the siding of the house and the handicapped ramp.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6557

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.
Inspection Number			
Property Address	18208 Oakland Ave		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

The panel was covered by a garden with 3 Full Size bushes covering up the panel completely.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6562
WO 38836

Date of Inspection	1/11/24	***Inspector Initials***	E.P.
Inspection Number			
Property Address	18215 Oakland Ave		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

There are 2 seperate panels, one is on metcom and the other is a high level panel for the homeowner

Repairs needed (if any) and estimated schedule for completion:

Alarm float light goes off but makes no sound.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

65564

Date of Inspection	1/11/24		***Inspector Initials***	E.P.
Inspection Number				
Property Address	18228 Oakland Ave			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6566

WO 31837

Date of Inspection	1/11/24	***Inspector Initials***	E.P.
Inspection Number			
Property Address	18233 Ocahland Ave		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Start Capacitor is NOT mounted

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6567

Date of Inspection	1/11/24	***Inspector Initials***	EP.
Inspection Number			
Property Address	18247 Oakland Ave		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6568

Date of Inspection	1/11/24	***Inspector Initials***	EP.	
Inspection Number				
Property Address	18365 Oakland Ave			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6569

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	E.P.
Inspection Number			
Property Address	18266 Oakland Ave		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What ~~type of~~ pump is this?

Meyers	Barnes	Retrofit	E1

What ~~is the~~ condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6571
WO 31838

Date of Inspection	1/11/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	17263 Oakwood Lodge Ln			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	(Poor)	Immediate Action

What is the condition of the cover?

Good	Missing	(Broken)	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault cover partially buried. Root growing into vault near inlet
Start capacitor in panel blown apart.

Repairs needed (if any) and estimated schedule for completion:

Panel needs new start capacitor

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6574

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	17265 Oak Wood Lodge Ln			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

No audible or visual alarm

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6675

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17267 Oak wood Lodge Ln			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6855

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	***Inspector Initials***	RH LN
Inspection Number			
Property Address	18104 Old Tall Timbers Rd		
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Aband

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6552

WO 31832

Date of Inspection	011824	***Inspector Initials*** E.Pool T.S.		
Inspection Number				
Property Address	44525 Oliver Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Control panel leaks, lid has minor damage from lawnmower

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6553

WO 31833

Date of Inspection	1/8/24		***Inspector Initials***	E.Pool T.S
Inspection Number				
Property Address	44528 Oliver Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

fiberglass Panel falling apart

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Tree within 1 foot of vault no damage to vault yet
spoke with customer & she will have tree removed.

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6554



Date of Inspection	01/8/24	***Inspector Initials*** E.Pool T.S		
Inspection Number				
Property Address	44581 Oliver Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Sundamaged

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Shrubs surrounding vault + valve

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6555

WO 31834

Date of Inspection	1/18/24	***Inspector Initials***	E.Pool
Inspection Number			
Property Address	44586 Oliver Dr.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Sun damaged

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

leaking around inlet, alarm is not very loud audibly.

Repairs needed (if any) and estimated schedule for completion:

Repair audible alarm, seal around inlet

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6181

St. Mary's County MetCom

Grinder Pump Field Inspection Form

WO 31613

Date of Inspection	6/18/24	***Inspector Initials***	CPool	T.S.
Inspection Number				
Property Address	44637 Oliver Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

lawn mower damage but still sealed

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Sun damaged

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots around inlet & junction box

Repairs needed (if any) and estimated schedule for completion:

repair seal around junction box & inlet to remove roots.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6182

WO 31615

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24	***Inspector Initials***	E.Pool T.S
Inspection Number			
Property Address	44547 Oliver Dr.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Sun damaged

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

1 Broken bolt in vault lid,
needs to be cleaned grease in vault
control Panel sun damaged.

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6856

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	18200 Peninsulas Ct.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6530

Date of Inspection	1/22/2024	***Inspector Initials***	DR EP	
Inspection Number				
Property Address	44901 Petite Point Ln			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6529

Grinder Pump Field Inspection Form

Date of Inspection	1/22/2024 ***Inspector Initials*** DOR EP
Inspection Number	
Property Address	44960 Pettit Point Ln
Weather Conditions	Rain Snow ~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6531

Date of Inspection	1/22/2024		***Inspector Initials***	DQ EP
Inspection Number				
Property Address	45040 Petite Point Ln			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6584

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	mm
Inspection Number			
Property Address	46325 PINETAMARE WAY		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6610

Date of Inspection	11/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17191 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6612

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24		***Inspector Initials***	mm
Inspection Number				
Property Address	17160 Piney Point RD #1 / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6613

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24 ***Inspector Initials*** mm
Inspection Number	
Property Address	17160 Piney Point Rd #2/Trot Line Way
Weather Conditions	Rain Snow Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6614

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	***Inspector Initials***	mam
Inspection Number			
Property Address	17162 Piney Point Rd / Trot Line Way		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

4615

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17164 Pine Pond Rd / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6616

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24 ***Inspector Initials*** mm
Inspection Number	
Property Address	17166 Piney Point RD / 7 rat Line Way
Weather Conditions	Rain Snow Sunny (Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	(No)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6617

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17178 Ping Pong Es / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6618

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/21/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17174 Piney Point Rd / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6619

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24		***Inspector Initials*** rmm	
Inspection Number				
Property Address	17176 Ring Point Rd / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6620

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17178 Ring Point Rd / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO CLEANED OUT
BUSH IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6621

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24		***Inspector Initials***	mm
Inspection Number				
Property Address	17180 Piney Point RD / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6622

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	17182 Piney Point RD / Trot Line Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6623

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\24\24		***Inspector Initials***	mam
Inspection Number				
Property Address	17194 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6624

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17200 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6625

WO 318169

Date of Inspection	1/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17203 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

COVER IS CRACKED

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

VAULT NEEDS TO BE PUMPED OUT
NO POWER GOING TO PANEL

Repairs needed (if any) and estimated schedule for completion:

COVER IS CRACKED
BUSH IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6026

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24	***Inspector Initials***	MBW	
Inspection Number				
Property Address	17213 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6628

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24		***Inspector Initials***	mcm
Inspection Number				
Property Address	17214 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6629

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	17216 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6630

WO 31870

Date of Inspection	1/24/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	17217 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

HOLE IN THE COVER.

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF ELECTRICAL PANEL
HOLE HOLE IN THE COVER

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6631
WO 31871

Date of Inspection	1/24/24		***Inspector Initials***	mem
Inspection Number				
Property Address	17222 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF PANEL
VAULT LIDS TO BE CLEANED

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6632

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24		***Inspector Initials***	mcm
Inspection Number				
Property Address	17232 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6633

Date of Inspection	1/24/24		***Inspector Initials***	mm
Inspection Number				
Property Address	17236 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6634
WO 31872

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17243 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

NEED TO INSTALL BOLTS AND WASHERS ON COVER

Repairs needed (if any) and estimated schedule for completion:

NEED TO INSTALL BOLTS AND WASHERS ON COVER

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6635

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\24\24	***Inspector Initials***	mm	
Inspection Number				
Property Address	17244 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6636

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24		***Inspector Initials***	mcm
Inspection Number				
Property Address	17346 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6637

WO 31873

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/04		***Inspector Initials***	mm
Inspection Number				
Property Address	17256 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE CLEANED OUT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6638

WO 31874

Date of Inspection	11/25/24	***Inspector Initials***	MM	
Inspection Number				
Property Address	17309 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

NOT FITTING PROPERLY

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

COVER NOT FITTING PROPERLY

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

COVER NOT FITTING PROPERLY

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6639

WO 31875

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/25/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17330A Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

SIDE OF VAULT IS CRACKED

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

VAULT IS CRACKED

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6640

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/25/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17330 B Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	(E1)

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	(No)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6641

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\25\24		***Inspector Initials***	mtm
Inspection Number				
Property Address	17334 Piney Point RD.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6642

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	17342 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6643

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/25/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17342 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6644

St. Mary's County MetCom

Grinder Pump Field Inspection Form

WO 31876

Date of Inspection	1/25/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17346 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

COVER MISSING OVER BREAKERS

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

COVER MISSING OVER BREAKERS

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

COVER MISSING OVER BREAKERS ON PANEL.

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6645

Grinder Pump Field Inspection Form

Date of Inspection	11/25/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17365 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6646

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/25/24		***Inspector Initials***	mwm
Inspection Number				
Property Address	17368 Piney Point Rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6647

Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	***Inspector Initials***		
Inspection Number				
Property Address	17371 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6648

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/25/24		***Inspector Initials***	mcm
Inspection Number				
Property Address	17382 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6649

Date of Inspection	11/05/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	17394 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6650

Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17408 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6651
WO 31877

Date of Inspection	1/25/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17484 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

ROOTS GROWING INTO VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6652

WO 31878

Date of Inspection	11/25/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17486 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE CLEANED OUT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6653

WO 31879

Date of Inspection	11/25/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17515 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

VISE GRIPS HOLDING RAIL

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

COVER IS BROKEN AND NEEDS TO BE REPLACED

Repairs needed (if any) and estimated schedule for completion:

VISE GRIPS HOLDING RAIL IN PLACE

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6054

WO 31880

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\25\24	***Inspector Initials***	mam
Inspection Number			
Property Address	17527 ~~17546~~ Piney Point RD		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE CLEANED OUT.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6655

Grinder Pump Field Inspection Form

Date of Inspection	1/25/24	***Inspector Initials***		
Inspection Number				
Property Address	17541 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6656

Date of Inspection	11/25/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	17555 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6657
31882

Date of Inspection	11/25/24	***Inspector Initials***	m+m	
Inspection Number				
Property Address	17558 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NEED TO PUT BOLTS IN COVER (NO BOLTS IN COVER)

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6658

Date of Inspection	1-25-24	***Inspector Initials***	RH LN
Inspection Number			
Property Address	17589 piney point Rd		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6659
WO 31883

Date of Inspection	11/25/24		***Inspector Initials***	mtm
Inspection Number				
Property Address	17594 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

HOME IS VACANT

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT IS FULL HOME IS VACANT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6660

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24		***Inspector Initials***	RH LN
Inspection Number				
Property Address	17609 piney point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6661

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	***Inspector Initials***	RH LN
Inspection Number			
Property Address	17619 piney point Rd		
Weather Conditions	Rain	Snow	Sunny / Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6662

Date of Inspection	1-25-24	***Inspector Initials***	RHL/N
Inspection Number			
Property Address	17702 piney point Rd		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6663

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24		***Inspector Initials***	RH LN
Inspection Number				
Property Address	17714 Piney point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6973
W/O: 31986.

Date of Inspection	1/31/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	17718 Piney Point Rd.
Weather Conditions	Rain Snow Sunny (Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	(Broken)	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault in shrubs and sticker thorn bushes

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

66664

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	***Inspector Initials***	RHCN
Inspection Number			
Property Address	17750 piney point Rd		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6606

WO 31867

Date of Inspection	1/22/24	***Inspector Initials***	JR RJ
Inspection Number			
Property Address	17802 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Loose hanging wires in panel.
Alarm Light and Alarm do not work.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6665

Date of Inspection	1/25/24	***Inspector Initials***	DH	
Inspection Number				
Property Address	17878 piney point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

66666

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	***Inspector Initials***	RH LN	
Inspection Number				
Property Address	17890 piney point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6667
WO 31884

Date of Inspection	1-25-24 ***Inspector Initials*** RH LH
Inspection Number	
Property Address	17900 piney point Rd
Weather Conditions	Rain Snow Sunny ~~Cloudy~~

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	~~Fair~~	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	~~Good~~	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Boots growing inside

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6668

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	***Inspector Initials***	RH LN
Inspection Number			
Property Address	17910 piney point Rd		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6669
WO 31885

Date of Inspection	1-25-24	***Inspector Initials***	RH LN
Inspection Number			
Property Address	17920 piney point Rd		
Weather Conditions	Rain	Snow	Sunny / Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots coming inside vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should ~~be~~ taken of each defect or identified action item(s).

St. Mary's County MetCom

6607

Grinder Pump Field Inspection Form

Date of Inspection	1-25-24	***Inspector Initials***	RH LN
Inspection Number			
Property Address	17930 piney point Rd		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6670
WO 31886

Date of Inspection	1/24/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	18395 Piney Point Rd.
Weather Conditions	Rain Snow ~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	Good	Fair	(Poor)	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	(Poor)	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vault is in bad condition. I&I coming in all around

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6673
WO 31888

Date of Inspection	1/24/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	18399 Piney Point Rd.		
Weather Conditions	Rain Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vault cover cracked and broken

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6675

Date of Inspection	1/23/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	18657 Piney Point Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6676

Grinder Pump Field Inspection Form

Date of Inspection	1/23/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	18661 Piney Point Rd.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6677
WO 31889

Date of Inspection	1/23/2024	***Inspector Initials*** LN CB		
Inspection Number				
Property Address	18960 Piney Point Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Both audible and visible alarms not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6671

Grinder Pump Field Inspection Form

WO 31887

Date of Inspection	1/23/2024	***Inspector Initials***	CB LN	
Inspection Number				
Property Address	18986 Piney Point Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6679

Grinder Pump Field Inspection Form

Date of Inspection	1/23/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	19066 Piney Point Rd.		
Weather Conditions	Rain Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6681
WO 31890

Date of Inspection	1/23/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	19084 Piney Point Rd.
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6682
WO 31891



Date of Inspection	1/23/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	19186 Piney Point Rd.
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Steady stream of I&I coming in near inlet pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6683

WO 31892

Date of Inspection	1/23/2024	***Inspector Initials***	LW CB
Inspection Number			
Property Address	19207 Piney Point Rd.		
Weather Conditions	Rain Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Alarm light not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6287.

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24	***Inspector Initials*** mam		
Inspection Number				
Property Address	16127 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6288

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16129 Piney Point Road			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6289

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16165 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6290

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24	***Inspector Initials***	mm
Inspection Number			
Property Address	16168 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6608

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	16168 Piney Point RD #2			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6609

Date of Inspection	11/21/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16170 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6291

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16332 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6292

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/8/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16340 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

BUSH IN FRONT OF RAMP

Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF RAMP

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6293

WO, 31725

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/8/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	16346 Piney Point Rd			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

ALARMS NOT WORKING

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6294

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/24	***Inspector Initials***	mmm	
Inspection Number				
Property Address	16374 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6295

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16378 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6296

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***		
Inspection Number				
Property Address	16384 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6297

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16402 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

60298

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11.1.24	***Inspector Initials***	mm	
Inspection Number				
Property Address	16434 Piney Point Rd (OCCUPIED DWELLING)			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6299

WO 31726

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/11/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	10424 Piney Point Rd (NOT OCCUPIED)			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

VAULT NEEDS TO BE PUMPED OUT THE PUMP DOESN'T WORK
ACCORDING TO THE HOME OWNER SO THEY CUT OFF THE POWER

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6300

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11\11\24	***Inspector Initials***	mam
Inspection Number			
Property Address	16432 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF PANEL BOX

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6301

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/11/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16434 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6302

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/1/24	***Inspector Initials***	mcm	
Inspection Number				
Property Address	16440 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES AROUND VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6303

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	16444 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF PANEL BOX

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6304

Grinder Pump Field Inspection Form

Date of Inspection	11/11/24		***Inspector Initials***	mem
Inspection Number				
Property Address	16446 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6305

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/04	***Inspector Initials***	mam
Inspection Number			
Property Address	16448 Piney Point RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF ELECTRICAL PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

63306

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/11/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	16450 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6307

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mcm	
Inspection Number				
Property Address	16452 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6308

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16454 Piney Point Rd.		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	(No)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6309
WO 31727

St. Mary's County MetCom

Grinder Pump Field Inspection Form

ABANDONED

Date of Inspection	1/12/24	***Inspector Initials***	mm
Inspection Number			
Property Address	16460 PINEY POINT RD		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	(No)

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

ABANDONED NEEDS TO BE PUMPED OUT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6310

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	16466 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF ELEC. PANEL.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6311

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16482 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

0312

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/2/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16484 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6313

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16498 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes (circled)	Retrofit	E1

What is the condition of the vault?

Excellent	Good (circled)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good (circled)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes (circled)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6314

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\12\24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16500 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6315

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16513 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes (circled)	Retrofit	E1

What is the condition of the vault?

Excellent	Good (circled)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good (circled)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes (circled)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6316

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/12/04	***Inspector Initials***	mam
Inspection Number			
Property Address	16530 Piney Point Rd		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6317
WO 31728

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/12/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16540 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE PUMPED OUT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6318

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16558 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6039

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16562 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6320
WO 31729

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/12/24	***Inspector Initials***	mtm	
Inspection Number				
Property Address	16584 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT IS FULL NEEDS TO PUMPED DOWN (NO POWER GOING TO PANEL)

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6321

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	16585 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6322

Date of Inspection	1/17/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16608 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6323

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	MAM
Inspection Number			
Property Address	16608 Piney Point Rd (ABANDONED)		
Weather Conditions	Rain	Snow	Sunny Cloudy

COULD NOT FIND THE VAULT

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6324

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	mkm
Inspection Number			
Property Address	16638 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6325

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/7/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16646 ~~16546~~ Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6326

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16650 Ping Point Rd		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes (circled)	Retrofit	E1

What is the condition of the vault?

Excellent	Good (circled)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good (circled)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No (circled)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6327

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	10676 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6328
WO 31730

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11-7-24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16660 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

COVER NEEDS TO BE REPLACED

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6329

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	mm
Inspection Number			
Property Address	16662 Piney Point RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6330

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/7/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16664 Piney Point RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6331
WO 31731

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16713 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	~~Good~~	Fair	Poor	Immediate Action

VAULT IS FULL OF WATER CANT SEE FIXTURES INSIDE

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

NO PANEL (NEW CONSTRUCTION)

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NEW CONSTRUCTION

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6388

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16728 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6389

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/16/04		***Inspector Initials***	mam
Inspection Number				
Property Address	16730 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NEEDS A RISER INSTALLED ON THE VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6341

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16750 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6393

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/16/24	***Inspector Initials***	mcm
Inspection Number			
Property Address	16760 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6394

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/16/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16800 Piney Point Rd (Ruddy Duck)			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

~~Duplex Pump~~ 2 pumps

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES WITHIN 5FT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

05416

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/15/24	***Inspector Initials***	mem
Inspection Number			
Property Address	16810 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers 63910 2 pumps	[illegible]	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

MISSING BOLTS IN COVER

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6397

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/6/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16874 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6399

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/16/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	16888 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64000

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16894 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6401

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/16/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16940 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6402

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/16/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16977 Piney Point RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6403

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/16/24	***Inspector Initials***	mcm
Inspection Number			
Property Address	16979 Piney Point RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6404

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\16\24	***Inspector Initials***	mm	
Inspection Number				
Property Address	16980 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64006
WO 31781

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***		
Inspection Number				
Property Address	16983 Piney Point RD (NEW CONSTRUCTION)			
Weather Conditions	Rain	Snow	Sunny	Cloudy

VAULT NEEDS TO BE PUMPED OUT BEFORE INSPECTION IS COMPLETE

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	(No)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

NO PANEL

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

VAULT NEEDS TO PUMPED OUT (NEW CONSTUCTION)

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6407

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16994 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	~~Barnes~~	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6408
WO 31783

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/16/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16995 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

NEEDS A RISER INSTALLED ON VAULT

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6410
WO 31785

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	mm
Inspection Number			
Property Address	16998 Piney Point Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NEEDS RISER INSTALLED OF VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6611

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17139 Piney Point Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6847

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	2/6/24		***Inspector Initials***	BH LN
Inspection Number				
Property Address	12880 Point lookout Rd. St Lukes Methodist church			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6585

Date of Inspection	1/11/2024	***Inspector Initials*** LN CB	
Inspection Number			
Property Address	~~17408~~ Poplar St. 17420		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault cover is surrounded by tall seagrass

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6586

Date of Inspection	1/11/2024		***Inspector Initials***	LN CB
Inspection Number	Poplar			
Property Address	17425 ~~Locust~~ St.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6587

WO 31843

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17428 Poplar St.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Both audible and visual alarms not working

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6588

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	17429 Poplar St.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6589

Date of Inspection	1/11/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	17448 Poplar St.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Plants and dirt piled up around vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6599

Date of Inspection	1/9/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17451 Poplar St.			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6591

Date of Inspection	1/9/2024	***Inspector Initials***		
Inspection Number				
Property Address	17465 Poplar St.			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6795

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	17473 River Dr.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6796

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	17485 River Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

vines growing around and all over vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6797

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17488 River Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6798
WO 31936

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17493 River Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Replace vault cover
vault cover has a big crack

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6799
WO 31937

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17494 River Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

ABANDONED, VAULT FULL

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6809



Date of Inspection	1/8/2024	***Inspector Initials***	LW CB	
Inspection Number				
Property Address	17497 River Dr.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6801

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	17508 River Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6802

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17526 River Dr.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6803

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17537 River Dr			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Customer has large potted plant on top of cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6804

Grinder Pump Field Inspection Form



Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17549 River Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6805

St. Mary's County MetCom

Grinder Pump Field Inspection Form

WO 31938

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17559 River Dr.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Audible alarm was not sounding. visual alarm is functioning
3 thread holes won't accept bolts for vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6806

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	17575 River Dr.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6807

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17680 River Dr.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6808

WO 31940



Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17585 River Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Bush covering half of vault cover. only has 3 bolts
Unable to open panel due to fence installed by customer

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6809

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	17591 River Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6842

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/26/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	19053 RIVER RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES AROUND VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

0843

Grinder Pump Field Inspection Form

Date of Inspection	11/26/24		***Inspector Initials***	mam
Inspection Number				
Property Address	~~16073~~ 16073 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	NO

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

PAINT IS ON THE POOR

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6707
WO 31904

Date of Inspection	1/29/24		***Inspector Initials***	
Inspection Number				
Property Address	18090 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	~~Barnes~~	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

VAULT IS BROKEN AT THE TOP

What is the condition of the cover?

Good	Missing	Broken	offset

WRONG COVER ON VAULT

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6710

Date of Inspection	11/29/24	***Inspector Initials*** mcm		
Inspection Number				
Property Address	TRAILER BESIDE 18090 RIVER RD			18096 River Rd
Weather Conditions	Rain	Snow	Sunny	Cloudy

CAMPER TRAILER ON LOT NO ADDRESS

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6711

Grinder Pump Field Inspection Form

Date of Inspection	~~1/29~~ 1/29/24		***Inspector Initials***	mar
Inspection Number				
Property Address	18102 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	~~Good~~	Fair	Poor	Immediate Action

s an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6712
WO 31907

Date of Inspection	1/29/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18103 RIVER RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

VAULT IS FULL OF WATER CAN'T SEE INTERIOR

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

NO POWER GOING TO THE GRINDER PUMP

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6714
WO 31908

Date of Inspection	1/29/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	18111 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

VAULT IS FULL NO POWER TO PUMP VAULT

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

CAN'T SEE INTERIOR VAULT IS FULL

s an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

VAULT IS FULL NO POWER GOING TO PUMP

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6715

Date of Inspection	11/29/24	***Inspector Initials*** mam		
Inspection Number				
Property Address	18125 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

s an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6716

Date of Inspection	1/29/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18131 Rivers Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6717

Date of Inspection	1\29\24		***Inspector Initials*** mem	
Inspection Number				
Property Address	18135 Rivers Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6718

Grinder Pump Field Inspection Form

Date of Inspection	1/29/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18140 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6719
WO 31909

Date of Inspection	1\24\24		***Inspector Initials***	mcm
Inspection Number				
Property Address	18145 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

CANT INSPECT THIS VAULT IS FULL
NO POWER TO THIS PANEL

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

NO POWER GOING TO THE PANEL SO THE VAULT IS FULL

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6720
WO 31910

Date of Inspection	1/29/24		***Inspector Initials*** mbm	
Inspection Number				
Property Address	18151 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

HOLES IN VAULT
ROOTS IN VAULT

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6721

WO 31911

Date of Inspection	11/29/24		***Inspector Initials***	mem
Inspection Number				
Property Address	18152 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF PANEL
HOLE IN SIDE OF VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6723

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/29/24		***Inspector Initials*** mm	
Inspection Number				
Property Address	18155 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6706

Date of Inspection	1\26\24		***Inspector Initials***	mam
Inspection Number				
Property Address	18159 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

COVER BUILT ON TOP OF VAULT (VERY HEAVY)

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6725
WO 31912

Date of Inspection	1/29/24		***Inspector Initials***	mm
Inspection Number				
Property Address	18167 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

VAULT IS FULL NO POWER TO PANEL

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

CANT DO INSPECTION VAULT IS FULL

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

VAULT IS FULL NO POWER TO PANEL

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6726

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/24		***Inspector Initials*** mrm	
Inspection Number				
Property Address	18183 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6728

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/04		***Inspector Initials*** mam	
Inspection Number				
Property Address	18186 River RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6730

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18175 Rivers Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6731

Date of Inspection	1\29\24		***Inspector Initials***	mam
Inspection Number				
Property Address	18177 River RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6732

Grinder Pump Field Inspection Form

Date of Inspection	11/29/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	18187 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6733

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18195 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6734

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/29/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18205 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6736

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18211 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6737.

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/9/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18213 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF PANEL.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6738

Date of Inspection	11/29/24	***Inspector Initials***	m+m	
Inspection Number				
Property Address	18215 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6739

Grinder Pump Field Inspection Form

Date of Inspection	1/29/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18231 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6741

WO 31917

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/29/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18237 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT IS CRACKED ON THE SIDE

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6742

Date of Inspection	1/29/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	18245 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	~~No~~

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6744

WO 31919

Date of Inspection	1/29/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18251 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

VAULT IS FULL CANT COMPLETE INSPECTION
NO POWER GOING TO PANEL

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

VAULT IS FULL NO POWER AT THE PANEL

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6810



Date of Inspection	1\30\24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18255 Rivers			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6811

Grinder Pump Field Inspection Form

Date of Inspection	1/30/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18260 River Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6812

Grinder Pump Field Inspection Form

Date of Inspection	11/20/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18265 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6813
WO 31943

Date of Inspection	11/30/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18267 River Dr			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

PUMP NOT WORKING BREAKERS WORKS OFF RESET BREAKER AND PUMP DID NOT COME ON (PROBABLY NO POWER TO THIS PANEL)

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6814

Date of Inspection	11/30/24		***Inspector Initials*** mtm	
Inspection Number				
Property Address	18269 River Dr			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VINES COVERING VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6815

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/30/24		***Inspector Initials***	
Inspection Number				
Property Address	18273 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6816

Date of Inspection	11/30/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18277 RIVERS			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6817

Date of Inspection	11/30/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18381 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

s an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6818

WO 31944

Date of Inspection	11/30/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18283 RIVER RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

VAULT IS FULL CANT COMPLETE INSPECTION

s an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

VAULT IS FULL NO POWER GOING TO PANEL
HOME IS VACANT

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6819

Date of Inspection	11/30/24		***Inspector Initials***	mem
Inspection Number				
Property Address	18288 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

s an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6820

Date of Inspection	11/30/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18293 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

s an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6821



Date of Inspection	11/30/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18299 Rowan Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

s an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6822

Date of Inspection	11/30/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18301 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

s an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6823



Date of Inspection	11/30/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18309 Rivers Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6824

Date of Inspection	11/30/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	18310 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6825

Grinder Pump Field Inspection Form

Date of Inspection	11/30/04		***Inspector Initials*** mtm	
Inspection Number				
Property Address	18313 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

SIDE OF VAULT IS BROKEN

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6826

Date of Inspection	1/30/24		***Inspector Initials***	mtm
Inspection Number				
Property Address	18314 RIVER RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6827

Grinder Pump Field Inspection Form

Date of Inspection	1/30/24	***Inspector Initials***		
Inspection Number				
Property Address	18319 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6828

Grinder Pump Field Inspection Form

Date of Inspection	1/30/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	18320 RIVERS			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6829

WO 31945

Date of Inspection	11/30/04		***Inspector Initials***	mam
Inspection Number				
Property Address	18325 River RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

VAULT IS FULL NO POWER TO PANEL

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6830

Date of Inspection	1/30/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18329 River RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6831

Grinder Pump Field Inspection Form

Date of Inspection	1/30/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18336 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6832

WO 31946

Date of Inspection	11/30/04	***Inspector Initials***	mam	
Inspection Number				
Property Address	18337 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Cover vs Brush

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6833
WO 31947

Date of Inspection	11/30/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	18341 RIVER RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

VAULT IS FULL HOUSE IS VACANT
VAULT IS BROKE AT TOP

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6834

Date of Inspection	1/30/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18342 Rwer Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6833
WO 31948

Date of Inspection	1/20/24		***Inspector Initials***	rmm
Inspection Number				
Property Address	18345 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE PUMPED OUT
NO POWER TO PANEL HOME IS VACANT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6836

Grinder Pump Field Inspection Form



Date of Inspection	11/30/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	~~183~~ 18347 Queen			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6837

Grinder Pump Field Inspection Form

Date of Inspection	11/30/24		***Inspector Initials***	mtm
Inspection Number				
Property Address	18351 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6838

Grinder Pump Field Inspection Form

Date of Inspection	1\30\24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18352 Elger Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6839

Grinder Pump Field Inspection Form

Date of Inspection	1/30/24		***Inspector Initials***	
Inspection Number				
Property Address	18357 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6840

Grinder Pump Field Inspection Form



Date of Inspection	1/30/24 ***Inspector Initials*** mam
Inspection Number	
Property Address	~~18356~~ 18358 Dwarf Rd
Weather Conditions	Rain Snow Sunny (Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6541

Date of Inspection	1\30\24		***Inspector Initials***	mm
Inspection Number				
Property Address	18365 River Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6979

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address	18375 River Rd.			
Weather Conditions	Rain	Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	~~Retrofit~~	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

~~Vented~~	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6980

Grinder Pump Field Inspection Form

Date of Inspection	1/26/2024		***Inspector Initials*** FS CB	
Inspection Number				
Property Address	18379 River Rd.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	(E1)

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6935

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	MLM	
Inspection Number				
Property Address	46238 RIVER RUN LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6936

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24	***Inspector Initials***	mzm	
Inspection Number				
Property Address	46239 RIVER ~~LANE~~ RUN LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6937

4/10: 31980

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	mtm	
Inspection Number				
Property Address	46265 RIVER RUN LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

THERE ARE ROOTS IN THE VAULT

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6945



Date of Inspection	11/26/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17767 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6793
WO 31934

Date of Inspection	11/30/24		***Inspector Initials***	
Inspection Number				
Property Address	17785 River Shore Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	~~Good~~	Fair	Poor	Immediate Action

Broken swing arm

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

VAULT NEEDS TO BE REPLACED

Repairs needed (if any) and estimated schedule for completion:

BROKEN SWING ARM

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6947
W/O: 31981

Date of Inspection	11/26/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17795 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

VAULT IS CRACKED

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT IS CRACKED

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6948

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/26/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	17804 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6949



Date of Inspection	11/26/24	***Inspector Initials*** mtm		
Inspection Number				
Property Address	17809 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES AROUND VAULT AND IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6950

Grinder Pump Field Inspection Form

Date of Inspection	11/26/04	***Inspector Initials***	mam
Inspection Number			
Property Address	17825 River Shore Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6951

Date of Inspection	1/24/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17834 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6952

Date of Inspection	1\24\24		***Inspector Initials***	mam
Inspection Number				
Property Address	17841 Bay River Shore Drive			
Weather Conditions	Rain	Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(~~Retrofit~~)	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	(No)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6953

Grinder Pump Field Inspection Form

Date of Inspection	11/26/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17844 RIVER SHORE DRIVE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT SURROUNDED BY BUSHES

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6954

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/26/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17855 RIVERSHORE DRIVE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6955

Date of Inspection	1\24\24		***Inspector Initials*** mm	
Inspection Number				
Property Address	17870 River Shores Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6956

Date of Inspection	11/26/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	17873 River Shores Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6957

Date of Inspection	1/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17882 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6958

Date of Inspection	1\24\24		***Inspector Initials*** mm	
Inspection Number				
Property Address	17887 River Shores Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6959

Date of Inspection	1/24/24	***Inspector Initials***	mvm	
Inspection Number				
Property Address	17901 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6960
W/O: 31982

Date of Inspection	1/26/24		***Inspector Initials***	mm
Inspection Number				
Property Address	17935 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

COVER AND TOP OF VAULT BROKEN

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6961

Grinder Pump Field Inspection Form

Date of Inspection	1/26/24		***Inspector Initials***	
Inspection Number				
Property Address	17943 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6962
W/O: 31983

Date of Inspection	11/26/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17959 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

VAULT IS BROKEN

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT IS BROKEN

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6963

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24		***Inspector Initials***	mam
Inspection Number				
Property Address	17983 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6964

Date of Inspection	11/26/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16003 RIVER SHORE DRIVE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	[redacted]

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6965



Date of Inspection	11/22/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18009 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6966

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/26/24		***Inspector Initials***	
Inspection Number				
Property Address	18019 River Shore Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES AROUND VAULT AND IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6967

Grinder Pump Field Inspection Form

Date of Inspection	11/26/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	18068 RIVER SHORE RD DRIVE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	[redacted]

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6862

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45260 St. Georges Ave.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

bushes next to vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6863

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	45266 St. Georges Ave		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6864

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	45272 St Georges Ave.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6865

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/8/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45278 St. Georges Ave.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Bushes next to vault

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6867



Date of Inspection	1/8/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	45284 St. Georges Ave.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6868

WO 31952

Date of Inspection	1/9/2024	***Inspector Initials***	LN UB
Inspection Number			
Property Address	45319 St. Georges Ave.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

piece of vault cover got chipped off. part of vault beneath the break also got chipped off

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6869

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	***Inspector Initials***	LN UB	
Inspection Number				
Property Address	45320 St Georges Ave			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6879
WO 31953

Date of Inspection	1/9/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45336 St Georges Ave			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

One Broken bolt stuck in thread hole for vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6871

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45345 St. Georges Ave.			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6872

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45383 St Georges Ave			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6873

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45401 St. Georges Ave			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6874
WO 31954

Date of Inspection	1/9/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45425 St Georges Ave.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Two bolt holes stripped out on vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6875

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	***Inspector Initials***	CN CB	
Inspection Number				
Property Address	45438 St Georges Ave.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6876
WO 31955



Date of Inspection	1/9/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45441 St Georges Ave.			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Audible alarm was not sounding. visual alarm light still lights up

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6877

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45480 St Georges Ave.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6878

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45451 St Georges Ave.			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6879

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/9/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45455 St Georges Ave			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6880

Date of Inspection	1/9/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45461 St. Georges Ave.			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6881

Date of Inspection	1/9/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	45462 St. Georges Ave.			
Weather Conditions	(Rain)	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6882

WO 319956

Date of Inspection	1/9/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	~~45467~~ St Georges Ave		
Weather Conditions	Rain 45473 Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

one bolt stuck in vault cover

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6593

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	JS RH	
Inspection Number				
Property Address	17838 St. Georges Park Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6594

Date of Inspection	1/23/24	***Inspector Initials***	JH
Inspection Number			
Property Address	17842 St. Georges Park Rd.		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6595

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	JH ZH
Inspection Number			
Property Address	17846 St. Georges Park Rd.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6705

Date of Inspection	1/23/24	***Inspector Initials***	JJ RH FF
Inspection Number			
Property Address	17871 St. Georges Park Rd.		
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6596

Grinder Pump Field Inspection Form

WO 31853

Date of Inspection	1/23/24	***Inspector Initials***	MRH
Inspection Number			
Property Address	17877 St. Mary's/Georges Park Rd.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

~~Breaker~~ Panel needs to be remounted to the house

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6597

Grinder Pump Field Inspection Form



Date of Inspection	1/24/24	***Inspector Initials***	RH SS
Inspection Number			
Property Address	17939 St. Georges park Rd		
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6592



Date of Inspection	1-24-24		***Inspector Initials***	RH SS
Inspection Number				
Property Address	17947 St. Georges Park Rd			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6598

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	
Inspection Number			
Property Address	17955 St. Georges park Rd		
Weather Conditions	Rain	Snow	Sunny ~~Cloudy~~

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6704

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	DL RH TH	
Inspection Number				
Property Address	17861 St. Georges Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6845

Grinder Pump Field Inspection Form

Date of Inspection	1\25\24	***Inspector Initials***	mam	
Inspection Number				
Property Address	17495 SAWDUST LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6883

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16455 Sayres Point Ln		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSH IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6884

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16459 Sayes Point Lane			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6885
WO 31963

Date of Inspection	1/11/24	***Inspector Initials***	mm
Inspection Number			
Property Address	16460 SAYRS POINT ~~ROAD~~ LANE		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

PANEL UNATTACHED FROM THE DWELLING

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6886

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/11/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16480 SAYRE POINT LN			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES AROUND VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6443

Date of Inspection	1/22/24	***Inspector Initials***	RH
Inspection Number			
Property Address	44535 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Float Light works, Alarm sound DOES NOT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

0491

Date of Inspection	1/22/24	***Inspector Initials***	JB RH
Inspection Number			
Property Address	44540 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6490

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	BB RH
Inspection Number			
Property Address	44570 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6445

Date of Inspection	1/22/24	***Inspector Initials***	JJ RM
Inspection Number			
Property Address	44571 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

~~No signs of I&I~~	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6489

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	JJ RH
Inspection Number			
Property Address	44584 Shallow Ford Ct		
Weather Conditions	Rain Snow ~~Sunny~~ Cloudy		

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6447

Date of Inspection	1/22/24	***Inspector Initials***	RH
Inspection Number			
Property Address	44591 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6488

WO 31814

Date of Inspection	1/22/24	***Inspector Initials***	JJ RH
Inspection Number			
Property Address	44594 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Light works Alarm does not work

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6487

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	JJ Zalb
Inspection Number			
Property Address	44604 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6449
WO 31800

Date of Inspection	12/22/24	***Inspector Initials***	JS RH
Inspection Number			
Property Address	44611 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Roots covering the whole inside of the vault but we can not reach them. 2 Large Bushes covering panel
Alarm Float light works, Alarm does not

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6486

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	
Inspection Number			
Property Address	44620 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

~~What~~ is the condition ~~of the vault~~?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6485
WO 31813

Date of Inspection	1/22/24	***Inspector Initials***	MP BA
Inspection Number			
Property Address	44624 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

A lot of roots in vault, must get cleaned SOON.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6457

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***		
Inspection Number				
Property Address	44633 Shallow Ford Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6459

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	~~RH~~ RH
Inspection Number			
Property Address	44639 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6483

WO 31812

Date of Inspection	1/22/24	***Inspector Initials***	SS JH
Inspection Number			
Property Address	44640 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Float light works, Alarm DOES NOT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6460

Date of Inspection	1/22/24	***Inspector Initials***	AP RH
Inspection Number			
Property Address	44645 Shallow Ford Ct.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6481

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***		
Inspection Number				
Property Address	44651 Shallow Ford Ct.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6887

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/7/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	45954 Stanley Point Lane			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6888

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/7/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	45956 Sleepy Point Lane			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6889

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/7/24	***Inspector Initials***	mwh	
Inspection Number				
Property Address	45958 Shatty Point Lane			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

7

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Picnic table over vault.

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6890

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	mrm	
Inspection Number				
Property Address	45962 Shanty Point Lane			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

ROSE BUSHES AROUND VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6891

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	mem	
Inspection Number				
Property Address	45928 Shanty Point Lane			
Weather Conditions	Rain	Snow	Sunny	Cloudy

DWELLING HAS 2 GRINDER PUMPS

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6892



Date of Inspection	1/17/24	***Inspector Initials***	mtm
Inspection Number			
Property Address	45980 Shanty Point Lane		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes (circled)	Retrofit	E1

What is the condition of the vault?

Excellent	Good (circled)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good (circled)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No (circled)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6893
WO 31965

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mtm
Inspection Number			
Property Address	46030 SHEAFFER LANE		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NEEDS TO BE CLEANED OUT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6894
WO 319666

Date of Inspection	11/12/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	46036 SHERIFFER LANE			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	(Poor)	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	(No)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

TOP OF VAULT NEEDS REPAIRS WHERE IT BOLTS ON

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6895
WO 31967

Date of Inspection	11/2/24	***Inspector Initials***	MAN	
Inspection Number				
Property Address	46048 SHEAFFER LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

VAULT NEEDS REPAIRING

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6896

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mem
Inspection Number			
Property Address	46053 SHEAFFER LANE		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes (circled)	Retrofit	E1

What is the condition of the vault?

Excellent	Good (circled)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good (circled)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No (circled)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6897

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/12/24	***Inspector Initials***	mam
Inspection Number			
Property Address	46055 SHEAFFER LANE		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6898

WO 319688

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/12/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	46059 SHAFFER LANE			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NEEDS CAP PUT ON CLEAN OUT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6508

St. Mary's County MetCom

Grinder Pump Field Inspection Form

WO 31824

Date of Inspection	1/23/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	16263 Ships View Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT NEEDS TO BE CLEANED OUT.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6511

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24		***Inspector Initials***	mtm
Inspection Number				
Property Address	16271 Ships View Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6513

Date of Inspection	1/23/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16288 Ships View Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6693

Date of Inspection	1/23/24	***Inspector Initials***	MRH
Inspection Number			
Property Address	44890 Shore Dr		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6694

Date of Inspection	1/23/24	***Inspector Initials***	MH
Inspection Number			
Property Address	44895 Shore Dr.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6695

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	DF RW
Inspection Number			
Property Address	44900 Shore Dr.		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6696

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	JH ZH	
Inspection Number				
Property Address	44901 Shore Dr			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6697

Date of Inspection	1/23/24	***Inspector Initials***	MM RH	
Inspection Number				
Property Address	44902 Shore Dr.			
Weather Conditions	Rain	Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

~~Good~~	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6696

Grinder Pump Field Inspection Form

WO 31903

Date of Inspection	1/23/24	***Inspector Initials***	JH RH
Inspection Number			
Property Address	44936 Shore Dr.		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6699

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	MW RH	
Inspection Number				
Property Address	44939 Shore Dr.			
Weather Conditions	Rain	Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6709



Date of Inspection	1/23/24	***Inspector Initials***	RJH
Inspection Number			
Property Address	44940 Shore Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6701



Date of Inspection	1/23/24	***Inspector Initials***		
Inspection Number				
Property Address	44945 Shore Dr.			
Weather Conditions	Rain	Snow	Sunny	~~Cloudy~~

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

~~Excellent~~	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non-Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6912

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***		
Inspection Number				
Property Address	UNKOWN ADDRESS (w/St. George ~~St Rd~~ park)			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Park

44980 Shore Drive.

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

1 Grinder Pump Vault with a Meyers pump. Rails, and an isolation valve inside of the vault. There is no panel for this grinder pump.

Repairs needed (if any) and estimated schedule for completion:

No Address, Grinder Pump Vault is located ACROSS from (44971 Shore Drive) on the right side of the road. ABANDONED Address found see front

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6702

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	HRH
Inspection Number			
Property Address	44988 Shore Dr.		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6433

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	JH ZH
Inspection Number			
Property Address	44996 Shore Dr.		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers (circled)	Barnes	Retrofit	E1

Vault?

What is the condition of the vault?

Excellent	Good	Fair	Poor (circled)	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent (circled)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes (circled)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Roots inside vault.

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6939

Grinder Pump Field Inspection Form

Date of Inspection	1\24\24		***Inspector Initials***	mam
Inspection Number				
Property Address	45285 STACY DR			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6949

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24		***Inspector Initials***	mm
Inspection Number				
Property Address	45297 STARK DR.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6941

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24		***Inspector Initials***	mcm
Inspection Number				
Property Address	45311 STARK DR.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6942

Date of Inspection	11/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	45321 STARK DR.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6943

Grinder Pump Field Inspection Form

Date of Inspection	11/24/24		***Inspector Initials***	mam
Inspection Number				
Property Address	45331 STARK DR.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6944

Grinder Pump Field Inspection Form

Date of Inspection	11/24/04		***Inspector Initials***	mtm
Inspection Number				
Property Address	45345 STARK DR.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6938

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/24	***Inspector Initials***	mm	
Inspection Number				
Property Address	45349 STARK DR.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

KAYAKS ON TOP OF VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

08846

Grinder Pump Field Inspection Form

Date of Inspection	1/25/24		***Inspector Initials***	LN
Inspection Number				
Property Address	17679 Stevart ~~pro~~ petroleum Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6921



Date of Inspection	1/30/2024	***Inspector Initials***	LN	CB
Inspection Number				
Property Address	44240 Tall Timbers Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	~~Retrofit~~	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6923

Date of Inspection	1/30/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	44316 Tall Timbers Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6924

Date of Inspection	1/30/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	44320 Tall Timbers Rd.
Weather Conditions	Rain Snow Sunny (Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6925

Date of Inspection	1/30/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	44328 Tall Timbers Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

le861

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/26/24		***Inspector Initials***	mrm
Inspection Number				
Property Address	44348 ~~Ranger Shores~~			Tall Timbers Rd
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6927

Date of Inspection	1/30/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	44415 Tall Timbers Rd.		
Weather Conditions	Rain	Snow	Sunny (Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6928

Grinder Pump Field Inspection Form

Date of Inspection	1 / 30 / 2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	44450 Tall Timbers Rd.
Weather Conditions	Rain Snow Sunny (Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

ESP switch for alarm

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6929

W/O: 31978

Date of Inspection	1/30/2024	***Inspector Initials***	LM	
Inspection Number				
Property Address	44477 Tall Timbers Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	(Fair)	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	(No)

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault is broken open at the top. vault cover broken
Abandoned no power

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6780
WO 3929

Date of Inspection	1/24/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	44660 Tall Timbers Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this? Submergible (duplex)

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	(Good)	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

(Yes)	No	Present, but not tested

Is the visible alarm present and functioning?

(Yes)	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	(No)

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

I&I coming in around inlet pipe

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6781

Grinder Pump Field Inspection Form

Date of Inspection	1/24/2024	***Inspector Initials***	LN CB
Inspection Number			
Property Address	44574 Tall Timbers Rd.		
Weather Conditions	Rain	Snow	Sunny (Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6782

Grinder Pump Field Inspection Form

Date of Inspection	1/24/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	44584 Tall Timbers Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this? Submergible (duplex)

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6783

Grinder Pump Field Inspection Form

Date of Inspection	1/24/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	44590 Tall Timbers Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

ESP switch for alarm

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6784

Date of Inspection	1/24/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	44600 Tall Timbers Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit) duplex	E1

What is the condition of the vault?

Excellent	Good	(Fair)	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6791

Grinder Pump Field Inspection Form

Date of Inspection	1/24/2024		***Inspector Initials*** LN CB	
Inspection Number				
Property Address	44680 ~~Bowes Rest Ln.~~ Tall Timbers Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

0492

Grinder Pump Field Inspection Form

Date of Inspection	1/24/2024 ***Inspector Initials*** LN CB
Inspection Number	44684 Tall Timbers Rd
Property Address	~~44680 Bowes Rest Ln~~
Weather Conditions	Rain Snow Sunny ~~Cloudy~~

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	(Retrofit)	E1

What is the condition of the vault? ✓

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

(Vented)	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	(Fair)	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	(No)

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

ABANDONED

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6786

Grinder Pump Field Inspection Form

Date of Inspection	1/24/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	44736 Tall Timbers Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6785

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/24/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	44744 Tall Timbers Rd.			
Weather Conditions	Rain	Snow	Sunny	(Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6787
WO 31930

Date of Inspection	1/24/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	44760 Tall Timbers Rd.
Weather Conditions	Rain Snow (Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Audible alarm not sounding

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6788

Grinder Pump Field Inspection Form

Date of Inspection	1/24/2024	***Inspector Initials*** LN CB	
Inspection Number			
Property Address	44780 Tall Timbers Rd.		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6930



Grinder Pump Field Inspection Form

Date of Inspection	1/31/2024 ***Inspector Initials*** LN CB
Inspection Number	
Property Address	44780B Tall Timbers Rd.
Weather Conditions	Rain Snow Sunny (Cloudy)

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Vault is in the woods behind telephone

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6504

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	16033 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6507

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24		***Inspector Initials***	mbm
Inspection Number				
Property Address	16040 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6509 #1
6510 #2

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\18\24	***Inspector Initials***	mrm	
Inspection Number				
Property Address	16048 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

2 VAULTS ON SAME ADDRESS

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6512

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16054 Thomas Rd		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6514

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	16056 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6516

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/16/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	16076 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6518

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/18/24	***Inspector Initials***	mcm	
Inspection Number				
Property Address	16084 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6521

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24		***Inspector Initials***	mm
Inspection Number				
Property Address	16087 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6522

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16088 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6524

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24		***Inspector Initials***	MJM
Inspection Number				
Property Address	16093 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF ELECTRICAL PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6525

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24		***Inspector Initials***	mrm
Inspection Number				
Property Address	16098 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

05526

Date of Inspection	1/18/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16100 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6527

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16165 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6528

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	MM	
Inspection Number				
Property Address	16113 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES AND FENCE IN FRONT OF ELECTRICAL PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

605 36

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24		***Inspector Initials***	mcm
Inspection Number				
Property Address	16114 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

0538

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16124 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6539

WO318829

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24		***Inspector Initials***	mam
Inspection Number				
Property Address	~~16130~~ THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT IS FULL AND HOUSE IS VACANT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6540

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24	***Inspector Initials***	MEM	
Inspection Number				
Property Address	16131 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6541

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24	***Inspector Initials***	MFM
Inspection Number			
Property Address	26140 THOMAS RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6542

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/22/24		***Inspector Initials***	MTM
Inspection Number				
Property Address	16144 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES IN FRONT OF ELECTRICAL PANEL

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6543

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/22/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16142 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6544
WO 31830

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/25/24		***Inspector Initials*** mcm	
Inspection Number				
Property Address	16172 Thomas RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

CLEAN OUT CAP BROKEN 4"

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6545

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\23\24		***Inspector Initials***	mam
Inspection Number				
Property Address	16174 Thomas Rd			
Weather Conditions	Rain	Snow	~~Sunny~~	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	(Good)	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	(No)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6546
WO 3183

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24		***Inspector Initials***	mdm
Inspection Number				
Property Address	16178 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

MUST TO BE REPLACED

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

PANEL IS NOT SERVICED TO THE HOME

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

TOP OF VAULT IS CRACKED AND NEEDS A RISER AND NON VENTED COVER

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6547

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	16180 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT SURROUNDED BY CRAB POTS

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6548

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24		***Inspector Initials***	m+m
Inspection Number				
Property Address	16182 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

VAULT SURROUNDED BY BAMBOO

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6551

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/23/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16197 THOMAS RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6558

St. Mary's County MetCom

Grinder Pump Field Inspection Form

MAIN HOUSE

Date of Inspection	1/23/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16212 THOMAS RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6559

St. Mary's County MetCom

Grinder Pump Field Inspection Form

RENTAL TRAILER

Date of Inspection	1/23/24	***Inspector Initials***	mam
Inspection Number			
Property Address	[redacted] 16213 THOMAS RD		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6560
WO 31835

St. Mary's County MetCom

Grinder Pump Field Inspection Form

RENTAL HOUSE

Date of Inspection	1/23/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16218 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

VAULT IS FULL OF WATER

Is an isolation valve present?

Yes	~~No~~

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Needs a Riser

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6561

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\23\24	***Inspector Initials***	mem
Inspection Number			
Property Address	16213 THOMAS RD		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers (circled)	~~Barnes~~ (circled)	Retrofit	E1

What is the condition of the vault?

Excellent	Good (circled)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good (circled)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes (circled)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

65563

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\23\24	***Inspector Initials***	mam
Inspection Number			
Property Address	16231 Thomas Rd		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes (circled)	Retrofit	E1

What is the condition of the vault?

Excellent	Good (circled)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good (circled)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No (circled)

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6517

WO 31823

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\23\24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16233 ~~[illegible]~~		Thomas Rd	
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

COVER AND RISER NEED TO BE INSTALLED

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6565

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\23\24	***Inspector Initials***	mm
Inspection Number			
Property Address	16255 Thomas Rd		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes (circled)	Retrofit	E1

What is the condition of the vault?

Excellent	Good (circled)	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good (circled)	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes (circled)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6515

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\23\24	***Inspector Initials*** mam	
Inspection Number			
Property Address	16361 ~~Thomas Conneck Way~~	Thomas Road	
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6570

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/23/04		***Inspector Initials*** mam	
Inspection Number				
Property Address	16262 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6572

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/23/24		***Inspector Initials*** mam	
Inspection Number				
Property Address	16291 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6573

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	16300 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6576

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16381 THOMAS RD			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

L0514

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24		***Inspector Initials***	mam
Inspection Number				
Property Address	16384 Thomas Rd			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6581

St. Mary's County MetCom

WO 3184D

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***	mam
Inspection Number			
Property Address	16416 Thomas Rd		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

NEEDS A RISER

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6987

WO 32027

Date of Inspection	2/8/24		***Inspector Initials*** E. Pool T.S.	
Inspection Number				
Property Address	45654 ~~St. Marys Pork Rd~~			Troopers Rd.
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

~~Meyers~~	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	~~No~~

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Bad Alarm float light works but no audible
fence with aggressive dog

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6789

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***		
Inspection Number				
Property Address	45029 Trooper Rd.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6790

Grinder Pump Field Inspection Form

Date of Inspection	1/23/24	***Inspector Initials***		
Inspection Number				
Property Address	45030 Trooper Rd.			
Weather Conditions	Rain	Snow	Sunny	~~Cloudy~~

Does MetCom own the grinder pump?

~~Yes~~	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

~~Excellent~~	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6899

Date of Inspection	1/11/2024	***Inspector Initials***	LN CB	
Inspection Number				
Property Address	45394 Walnut St.			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

Meyers	(Barnes)	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6909

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024		***Inspector Initials***	LN CB
Inspection Number				
Property Address	46395 Walnut St.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6901

W/O: 31969

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/11/2024	***Inspector I***		
Inspection Number				
Property Address	45404 Walnut St.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

small part of vault cover and vault below it chipped off
visual alarm light not flashing. audible sound still works

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

04461

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DF CR
Inspection Number			
Property Address	17515 Whitestone Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

There are about 6 Bushes and 2 A/C units blocking access to the panel.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

04602

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	JJ CR
Inspection Number			
Property Address	17527 Whitestone Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Trash Cans and Loose Debris blocking access to panel.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6463
WO 318006

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	DS CR
Inspection Number			
Property Address	17533 Whitestone Drive		
Weather Conditions	Rain	Snow	~~Sunny~~ Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

1 Large Bush blocking access to panel
Alarm Float Light & Buzzer DO NOT WORK

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6464

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	CR
Inspection Number			
Property Address	17551 Whitestone Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

2 Bushes blocking access to panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64165

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/18/24	***Inspector Initials***	CR
Inspection Number			
Property Address	17561 Whitestone Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64166
WO 31807

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1-17-24	***Inspector Initials***	CMR SS	
Inspection Number				
Property Address	17571 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm float light & buzzer DO NOT WORK

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64167
WO 319162

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1-17-24	***Inspector Initials***	CMR SS	
Inspection Number				
Property Address	17581 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Vault Lid is missing a quarter of the lid.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6468
WO 31808

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1-17-24	***Inspector Initials***	CMR SS
Inspection Number			
Property Address	17585 Whitestone Drive		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers (circled)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent (circled)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent (circled)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes (circled)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Float light and Buzzer do not work

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6469

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CMR SS
Inspection Number			
Property Address	17587 Whitestone Drive		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64.10

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1-17-24	***Inspector Initials***	CMR SS	
Inspection Number				
Property Address	17590 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6471
WO 31809

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS	
Inspection Number				
Property Address	17597 Whitestone ~~Place~~ Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Float was lighting up panel, but making no sound.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

0472

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS
Inspection Number			
Property Address	17620 Whitestone Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6473

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR JS
Inspection Number			
Property Address	17625 Whitestone Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6 of 14

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials*** CR SS		
Inspection Number				
Property Address	17645 Whitestone Drive			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6475

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/7/24	***Inspector Initials***	CR SS	
Inspection Number				
Property Address	17649 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

2 Bushes blocking access to panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64760

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials*** CB SS		
Inspection Number				
Property Address	17651 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6477

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS	
Inspection Number				
Property Address	17665 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

0478

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24		***Inspector Initials***	CR SS
Inspection Number				
Property Address	17675 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

1 Bush blocking access to the panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6479

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials*** CR SS		
Inspection Number				
Property Address	17685 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

06480
WO 31810

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials*** CR SS		
Inspection Number				
Property Address	17695 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

1 Bush blocking access to the panel
Alarm float light works but there is no sound

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6482
WO 31811

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS	
Inspection Number				
Property Address	17715 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

10 Ft Tall Pine Tree blocking the whole panel
Alarm Float light works but no sound.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6484

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS	
Inspection Number				
Property Address	17725 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6442

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/15/24	***Inspector Initials***	CR ST	
Inspection Number				
Property Address	17735 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Big AC unit fan right infront of panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6493

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24		***Inspector Initials*** CR SS	
Inspection Number				
Property Address	17745 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

1 Average size bush blocking access to panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64494

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS	
Inspection Number				
Property Address	17749 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6445

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials*** CR SS		
Inspection Number				
Property Address	17751 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	~~Non Vented~~

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

~~Yes~~	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

2 Average size Thorn bushes blocking access to panel.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

64496
WO 318160

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS	
Inspection Number				
Property Address	17753 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

The panel is located behind multiple boxes on the porch.
The Alarm Flood light works, but no sound when flood is made.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6447

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials*** CR SS	
Inspection Number			
Property Address	17759 Whitestone Drive		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

1 small bush blocking access to the panel

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6448
WO 31817

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS	
Inspection Number				
Property Address	17760 Whitestone Dr.			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

There is no Alarm Float Present in the vault

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6499
WO 31818

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials*** CR SS		
Inspection Number				
Property Address	17761 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Float light works when made, but no sound

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6500
WO 31819

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials*** CR SS		
Inspection Number				
Property Address	17763 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Panel is messy. loose wires, hanging capacitors and relays. some wires are cut and NOT capped off.
Alarm Float light works when made, but there is no sound.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6501
WO 31820

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials*** CR SS		
Inspection Number	4			
Property Address	17763 Whitestone Drive			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

When The Alarm Float is made the light on the panel is on, but there is no sound.

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6902
WO31970

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CA SS	
Inspection Number				
Property Address	44474 Whitestone Place			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Float light works sound DOES NOT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6903

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS	
Inspection Number				
Property Address	44476 Whitestone Place			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6904
WO 31971

Date of Inspection	1/17/24	***Inspector Initials***	CR SS
Inspection Number			
Property Address	44477 Whitestone Place		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Vault needs a riser, located in mulchbed beside driveway

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6905

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS
Inspection Number			
Property Address	44478 Whitestone Place		
Weather Conditions	Rain	Snow	(Sunny) Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

(Excellent)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6906

WO 31972

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CR SS
Inspection Number			
Property Address	44479 Whitestone Place		
Weather Conditions	Rain Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6907
WO 31973

Date of Inspection	1/17/24	***Inspector Initials*** CR SS	
Inspection Number			
Property Address	44480 Whitestone Place		
Weather Conditions	Rain	Snow	Sunny (circled) Cloudy

Does MetCom own the grinder pump?

Yes (circled)	No	Unknown, add comments in observations

What type of pump is this?

Meyers (circled)	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent (circled)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good (circled)	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented (circled)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent (circled)	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes (circled)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm Flood light works, buzzer (does not)

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6908
WO 31975

Date of Inspection	1/17/24	***Inspector Initials*** CR SS	
Inspection Number			
Property Address	44482 Whitestone Place		
Weather Conditions	Rain	Snow	Sunny Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Crab Pots and Garden Pots blocking panel
Alarm Float Light works, Alarm Buzzer DOES NOT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6910

WO 31976

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1/17/24	***Inspector Initials***	CMR SS	
Inspection Number				
Property Address	44491 Whitestone Place			
Weather Conditions	Rain	Snow	(Sunny)	Cloudy

Does MetCom own the grinder pump?

(Yes)	No	Unknown, add comments in observations

What type of pump is this?

(Meyers)	Barnes	Retrofit	E1

What is the condition of the vault?

(Excellent)	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

(Good)	Missing	Broken	offset

What type of cover is installed?

Vented	(Non-Vented)

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	(Good)	Fair	Poor	Immediate Action

Is an isolation valve present?

(Yes)	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Alarm float light and buzzer both (DO NOT WORK

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6913

Date of Inspection	11/26/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	18029 William Howard Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6914

Date of Inspection	1/24/24		***Inspector Initials***	mm
Inspection Number				
Property Address	18041 William Howard Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	[illegible]

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

BUSHES AROUND VAULT

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6915

Grinder Pump Field Inspection Form

Date of Inspection	11/26/24		***Inspector Initials***	mam
Inspection Number				
Property Address	18049 William Howards Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6916

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	1\24\24		***Inspector Initials***	mm
Inspection Number				
Property Address	18057 William Howards Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6917

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/26/24		***Inspector Initials***	mcm
Inspection Number				
Property Address	18067 WILLIAM HOWARD'S WAY			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6918

Grinder Pump Field Inspection Form

Date of Inspection	11/26/24		***Inspector Initials***	mm
Inspection Number				
Property Address	18075 WILLIAM HOWARD WAY			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

6919

Grinder Pump Field Inspection Form

Date of Inspection	1/26/24	***Inspector Initials***	MBM	
Inspection Number				
Property Address	16097 William Howard Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6514

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/23/24		***Inspector Initials***	mam
Inspection Number				
Property Address	46220 Wind Whisper Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

THERE IS A BUSH BY THE VALVE

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

St. Mary's County MetCom

Grinder Pump Field Inspection Form

6529

WO 31826

Date of Inspection	1/23/24	***Inspector Initials***	mam	
Inspection Number				
Property Address	46230 WIND WHISPER WAY			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

THERE ISNT A PUMP IN THE VAULT

What type of pump is this? WAS A BARNES

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

No Pump

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).

6523

St. Mary's County MetCom

Grinder Pump Field Inspection Form

Date of Inspection	11/23/24		***Inspector Initials***	mam
Inspection Number				
Property Address	46233 Windwhisper Way			
Weather Conditions	Rain	Snow	Sunny	Cloudy

Does MetCom own the grinder pump?

Yes	No	Unknown, add comments in observations

What type of pump is this?

Meyers	Barnes	Retrofit	E1

What is the condition of the vault?

Excellent	Good	Fair	Poor	Immediate Action

What is the condition of the cover?

Good	Missing	Broken	offset

What type of cover is installed?

Vented	Non-Vented

Condition of interior fixtures (guide rails, electrical connections, etc.)

Excellent	Good	Fair	Poor	Immediate Action

Is an isolation valve present?

Yes	No

What is the condition of the electrical panel?

Excellent	Good	Fair	Poor	Immediate Action

Is the audible alarm present and functioning?

Yes	No	Present, but not tested

Is the visible alarm present and functioning?

Yes	No	Present, but not tested

Are there any accessibility issues (shrubs, trees, fences)?

Yes, note issues below in observations	No

Are there any obvious signs of I&I (ie. clearwater flow)?

No signs of I&I	Minor signs of I&I (weeping or trickle)	Major (gushing)

Other Observations, any "Immediate Action" taken should be described:

Repairs needed (if any) and estimated schedule for completion:

Photos should be sent to opadmin@metcom.org with the address of the grinder pump in the subject line. One photo should be taken of each defect or identified action item(s).